Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR DEPARTMENT OF LAND MANAGEMENT

**OCD Artesia** 

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

	Expires:	July	31,	20
Lease	Serial No.	_		
18.71	COEAGOOD			

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No.	5. Lease Serial No. NMLC054988B  6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agree	7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well  ☐ Gas Well ☐ Other					8. Well Name and No. • JENKINS B FEDE	8. Well Name and No. JENKINS B FEDERAL 9			
Name of Operator     COG OPERATING LLC	9. API Well No. 30-015-29755-0	9. API Well No. 30-015-29755-00-S1							
3a. Address ONE CONCHO CENTER 600 MIDLAND, TX 79701	3b. Phone No Ph: 432-68	. (include area code 5-4332	)		10. Field and Pool, or Exploratory LOCO HILLS GLORIETA-YESO				
4. Location of Well (Footage, Sec., T.	R., M., or Survey Description	)			11. County or Parish,	and State			
Sec 20 T17S R30E SWNW 23	ÉDDY COUNT)	EDDY COUNTY, NM							
1									
12. CHECK APPE	ROPRIATE BOX(ES) TÇ	) INDICATE	NATURE OF	NOTICE	, REPORT, OR OTHE	R DATA			
TYPE OF SUBMISSION	TYPE OF ACTION								
Notice of Intent	☐ Acidize	· 🗖 Dee	pen	□ Pro	duction (Start/Resume)	■ Water :	Shut-Off		
	Alter Casing	☐ Frac	☐ Fracture Treat ☐ Reclam		lamation	🗖 Well In	ntegrity		
☐ Subsequent Report	Casing Repair	□ New	New Construction		omplete	Other	•		
☐ Final Abandonment Notice	Change Plans	Plug	Plug and Abandon   Ten		nporarily Abandon ·				
1	Convert to Injection.	🗖 Plug	Back	■ Wa	ter Disposal				
If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit COG Operating LLC, respectful Procedure:  Rod Pull Procedure  ? MIRU WSU, NU BOP  ? POOH w/ rods and pump on o Let Engineering know the quark PRU Wireline ? Set CIBP @ 4+00?	ck will be performed or provide operations. If the operation revandomment Notices shall be file inal inspection.)  ully requests to recomplete LD on location antity and conditions of the part of 4080?	the Bond No. or sults in a multipled only after all the to the San	Andres.  SEI CO	A Require completion ling reclam  ACCO  E ATT  NDIT	d subsequent reports shall be in a new interval, a Form 316 nation, have been completed, which is the property of the property	filed within 30-4 shall be fill and the operate	0 days led once or has  L RVATION RICT		
14. I hereby certify that the foregoing is  Co  Name(Printed/Typed) KANICIA (	Electronic Submission #2 For COG O mmitted to AFMSS for pro-	PERATING L	.C, sent to the C	arlsbad 06/06/201		RECEIVE	D		
Signature (Electronic S	ubmission)		Date 05/05/2	d14	<u>V DDDUNED</u>				
	THIS SPACE FO	R FEDERA	L OR STATE	<b>OFFIGE</b>	USE THO VED	7			
Approved By	<del></del>		Title		/JUL 2 2 2014	2/7 Date	<del></del>		
Conditions of approval, if any, are attached	Approval of this notice does	not warrant or	THE	+-+	// LUIN	1/20			
certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of the conduc	itable title to those rights in the	subject lease	Office	0110	MANUAL MA	I fort	m .		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department of agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

### Additional data for EC transaction #244495 that would not fit on the form

#### 32. Additional remarks, continued

- ? Pull up 4? to circulate hole clean with fresh water, and displace w/ 2% KCL and 1% packer corrosion inhibitor.
- ? Test Casing to 4,200 psi and report back to engineering if the pressure holds. ? Secure wellbore
- ? RDMO WSU

Tentative Recompletion Procedure

- ? NU frac valve, and test casing to 4200 psi
- ? Rig up wireline.
- ? RIH'w/ perforating guns and perforate San Andres Zone from 3708?-3801? w/ 3 spf, 60? phasing,
- 21holes.

- ? Acidize w/ 1500 gals of 15% HCl. ? Frac zone w/ 181,250 # of sand. ? Record ISIP and FG, Get 5, 10, 15 min SIP

- ? Rig up Wireline ? RIH w/ WL and set Composite Plug @ 3650? ? Perforate San Andres Zone from 3094?-3277? w/ 3 spf, 60? phasing, 24 holes.

- ? Acidize w/ 1500 gals of 15% HCi. ? Frac zone w/ 181,250 # of sand. ? Record ISIP and FG, Get 5, 10, 15 min SIP
- ? RU WSU
- ? RIH with Production tog and tag for fill w/ bailer at knocked Composite plugs @ 3650? and 3900? ? Clean out fill to new PBTD @ 4060?
- ? POOH bailer and tbg
- ? POOR baller and tog ? RIH with production tubing and locate intake at 3850?. ? Set TAC @ 3000? ? RIH w/ rods and pump.

- ? RDMO rig.

## COG Operating LLC

## Lease & Well # Jenkins B Federal #9 Sec 20E, 17S, 30E, Eddy Co., NM Spud: 10/27/97 3001529755 Elevation - 3627' KB-8 5/8" 24# J-55 @ 463', 350 sx cmt, circ. 60 sx Marker jt - 3260' DV tool - 4151' Yeso 4296 - 4708', 73 holes Acidized w/3000 gal 15% HCl Treat w/32,000 gal 20% HCL, 54,000 gal LG, 5,000 gal 15% HCL 1st stage: 150 sx 50/50/2 CL C, circ 60 sx

PBTD - 4841'

2nd stage: 600 sx 35/65/6 CL C, 375sx 50/50/2,circ 140 sx

5 1/2" 17# csg @ 4854'.

### **COG Operating LLC**

## Jenkins B Federal #9 Lease & Well # Sec 20E, 17S, 30E, Eddy Co., NM Spud: 10/27/97 3001529755 Elevation - 3627 8 5/8" 24# J-55 @ 463', 350 sx cmt, circ. 60 sx 3094'-3277' w/ 3 SPF, 60 degree phasing, 21 Holes Acidize with 1500 gallons of 15% HCL Frac zone with 181,250 # of proppant Marker jt - 3260' 3708'-3801' w/ 3 SPF, 60 degree phasing, 21 Holes Acidize with 1500 gallons of 15% HCL Frac zone with 181,250 # of proppant CIBP @ 4100' w/ 40' of CMT DV.tool - 4151' Yeso 4296 - 4708', 73 holes Acidized w/3000 gal 15% HCI Treat w/32,000 gai 20% HCL, 54,000 gai LG, 5,000 gai 15% HCL 1st stage: 150 sx 50/50/2 CL C, circ 60 sx 2nd stage: 600 sx 35/65/6 CL C, 375sx 50/50/2,circ 140 sx PBTD - 4841' 5 1/2" 17# csg @ 4854'.

Jenkins B Federal 9 30-015-29755 COG Operating, LLC. July 22, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by October 22, 2014.

- 1. Operator shall set a CIBP at 4,246' and place 25sx Class C cement on top. Tag required at a minimum of 4,000' to seal the top of the Glorietta and DV tool.
- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a **2000** (**2M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 9. Subsequent sundry required detailing work done and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
- 10. See attached for general requirements.

JAM 072214

### BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### **General Requirements for Plug Backs**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the  $90^{th}$  day provide this office, prior to the  $90^{th}$  day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat** Class "C", for up to 7,500 feet of depth or **Neat** Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed</u>.
- 7. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.