	· .				NON		•	
•			-11	ONSERVA			*	
2	Form 3160-5	UNITED STATES ARTESIA DEERVATION						
	(August 2007) DE	UNITED STATES ARTESIA DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT JUL 25 2014				FORM APPROVED OMB NO. 1004-0135		
	BUREAU OF LAND MANAGEMENT JUL D				Expires: July 31, 2010 5. Lease Serial No.			
	SUNDRY NOTICES AND REPORTS ON WELLS				NMLC064756			
	SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-entry GnIVED abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name			
	SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.			
	1. Type of Well					8. Well Name and No. WILSON 4		
	2 Name of Operator Contact: STAN WAGNER					9. API Well No.		
	2. Name of Operator EOG RESOURCES INCORPO	30-015-05867-00-S1						
	Ph: 432-68			(include area code) 6-3689		10. Field and Pool, or N MASON	Exploratory .	
	MIDLAND, TX 79702 4. Location of Well <i>(Footage, Sec., T</i>		· ·			11. County or Parish,		
	Sec 24 T26S R31E SWSE 66	v ,		EDDY COUNT	Y, NM			
	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
	TYPE OF SUBMISSION TYPE OF ACTION							
						• (0) • (D) >		
	Notice of Intent			-		ion (Start/Resume)	U Water Shut-Off	
	🛛 Subsequent Report	☐ Alter Casing	-	ture Treat	C Reclam			
	☐ Final Abandonment Notice	 Casing Repair Change Plans 	_	v Construction g and Abandon		arily Abandon	□ Other	
		Convert to Injection		g Back	U Vater I	•	4-9-14	
	 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 3/17/14 MIRU for P&A. RIH and tag cement plug at 3876'. POOH. 							
	3/18/14 Perform surface well 3/19/14 Wait on BLM approve approval from Jim Amos. 3/20/14 RIH and perforate at Notified BLM. Instructed to sp Pumped 50 sx Class C cemer 3/21/14 RIH and tag cement tubing at 2300'. Notify BLM re perforating at 2300'. Unable to spot cement plug at 2300'.	Received Accepted as to plugging of the well bore, e. Liability under bond is retained until Surface restoration is completed.						
	Pumped 50 sx Člass C cement from 2300 to 1194'.					UE 10-6-	<u>1</u>	
	14. I hereby certify that the foregoing is true and correct. Electronic Submission #247151 verified by the BLM Well Information System For EOG RESOURCES INCORPORATED, sent to the Carlsbad Committed to AFMSS for processing by LINDA DENNISTON on 06/03/2014 (14LD0198SE)							
	Name (Printed/Typed) STAN WA		ATORY AN		· · · · · · · · · · · · · · · · · · ·			
	Signature (Electronic	Date 05/28/2	014					
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
	APProved By ACCEPTED			JAMES A AMOS TitleSUPERVISOR EPS Date 07/17/2014				
	Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to cond	Office Carlsba	d					
	itle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
	** BLM REV	ISED ** BLM REVISE	D **.BLM R	EVISED ** BLM		O ** BLM REVISE	D **	
					,			
		•						

· .

.

Additional data for EC transaction #247151 that would not fit on the form

32. Additional remarks, continued

4

3/22/14 RIH and tag cement plug at 1857'. Notified BLM, instructed to proceed with P&A operations. POOH to 1050'. Perforate at 1120'. Unable to establish injection rate. BLM instructed to spot cement plug at 1190'. Pump 50 sx Class C cement from 1190 to 600'. WOC 5 hrs. RIH to 775'. Did not tag Cement top at 720'. RIH and perforate at 100'. Circulate thru perforations.
3/24/14 RIH and tag cement plug at 718'. Plug tag witnessed by Terry Wilson - BLM. POOH. RIH and pump 35 sx Class C cement from 100' to surface. Close well in, rig down.
4/09/14 Cement to surface on both casing strings. Cut off wellhead, weld on P&A marker, clean location. Well P&A.