

NM OIL CONSERVATION

ARTESIA DISTRICT

AUG 05 2014

 Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

1 AB1421854563

OPERATOR
☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220
Facility Name: Big Eddy Unit 164 Tank Battery

Contact: Tony Savoie
Telephone No. 575-887-7329
Facility Type: Exploration and Production

Surface Owner: Federal

Mineral Owner: Federal

API No. 30-015-35592

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	27	21S	29E	1650	South	1650	East	Eddy

 Latitude N 32.447365 Longitude W 103.968959
NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 1/2 bbl of crude oil and 10.5 bbls produced water	Volume Recovered: None
Source of Release: Produced water tank	Date and Hour of Occurrence: 7/27/14 time unknown	Date and Hour of Discovery: 7/27/14 at 12:54 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The well unloaded and caused the water tank to overflow. Water hauler failed to off-load water. Pumper called the water transport company to verify when water needs to be hauled.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 515 sq.ft. of the earthen containment around the production tanks. All of the fluid soaked into the ground. The tanks will be evaluated for relocation and placement inside O perm containment. The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by <u>[Signature]</u> Regional Specialist	
Title: Waste Management and Remediation Specialist		Approval Date: <u>8/7/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>tasavoie@basspet.com</u>		Conditions of Approval: Remediation Per O.C.D. Rule & Guidelines	
Date: <u>8/4/14</u>	Phone: <u>432-556-8730</u>	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

 SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 9/7/14

2RP-2414