

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 11 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1425529738

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: OXY USA Limited Partnership	Contact: Chris Jones
Address: 102 S. Main St. Carlsbad, NM 88220	Telephone No.: 575-628-4121
Facility Name: Conoco 10 State #2H	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No.: 30-015-39112
----------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter M	Section 10	Township 19S	Range 29E	Feet from the 580'	North/South Line South	Feet from the 660'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.669563 N Longitude -104.0691133 W

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 70 bbls	Volume Recovered: 70 bbls
Source of Release: Leak in Steel Tank	Date and Hour of Occurrence 9/2/14	Date and Hour of Discovery 9/2/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Email: Mike Bratcher OCD	
By Whom? Chris Jones	Date and Hour: 9/3/2014 6:58 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A steel water tank was found to be leaking due to internal corrosion resulting in a release of 70 barrels of produced water inside the lined containment of the facility. The well was shut in, the tank was repaired and put back into service. A vac truck was immediately called to the location and recovered 70 barrels of fluids.

Describe Area Affected and Cleanup Action Taken.*
No further actions are required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones		OIL CONSERVATION DIVISION	
Printed Name: Chris Jones		Approved by Environmental Specialist: <i>Mike Bratcher</i>	
Title: HES Specialist		Approval Date: 9/12/14	Expiration Date: N/A
E-mail Address: Christopher.Jones@oxy.com		Conditions of Approval: FINAL	
Date: 9/3/2014 Phone: 575-628-4121		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RR-2482