

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OCT 10 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

NAB/428737173

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Sterling Silver 33 Federal #1H	Facility Type	Well

Surface Owner	BLM	Mineral Owner		API No.	30-015-39831
---------------	-----	---------------	--	---------	--------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	33	23S	31E	360	South	590	East	Eddy County, NM

Latitude N 32.25453° Longitude W 103.77560°

## NATURE OF RELEASE

Type of Release	Oil	Volume of Release	120 bbls	Volume Recovered	100 bbls
Source of Release	Failure of head switch on a tank at the well	Date and Hour of Occurrence	09/18/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson- NMOCD, Sol Hughes- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	09/19/2014 @ 9:25 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The head switch on a tank at the well failed causing the tank to spill 120 bbls of oil onto the ground. The switch was reset and a vacuum truck recovered 100 bbls of oil.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 30' x 25' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature:

Printed Name: Chancey Summers

Title: HES Advisor

E-mail Address: Chancey.Summers@oxy.com

Date: 10-10-14 Phone: (575) 397-8216

Approved by Environmental Specialist:

Approval Date: 10/14/14

Expiration Date: NA

Conditions of Approval:

Attached ☐

Remediation per O.C.D. Rules & Guidelines  
SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 11/14/14

\* Attach Additional Sheets If Necessary

2RP-2545