
Submit 1 Copy To Appropriate District Office	State of New Mexico Form C		Form C-103		
<u>District I</u> – (575) 393-6161	Energy, Minerals and	Natural Resources	WELL API NO.	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OH CONCEDIAL	NON DIVIGION	30-015-23651		
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION DIVISION		5. Indicate Type of	f Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE X 6. State Oil & Gas	FEE L	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sama i e, iv		B-2023	Lease No.	
(DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICAT		OR PLUG BACK TO A	7. Lease Name or Old Loco Unit	Unit Agreement Name	
PROPOSALS.)  1. Type of Well: Oil Well X Gas Well  Other			8. Well Number 021		
2. Name of Operator Tandem Energy Corporation			9. OGRID Numbe	9. OGRID Number	
3. Address of Operator 2700 South Post Oak Blvd, Suite 1000, Houston, Texas 77056			10. Pool name or Wildcat Grayburg-Jackson SR-Q-G-SA Pool		
4. Well Location		,			
	_2310 feet from the North	line and 1650 feet from	the East line		
Section 32 Township 17		NMPM	Eddy County	Markey of Constitution and State of Constitution	
	11. Elevatión (Show wheth 3578' GR	er DR, RKB, RT, GR, etc	c.)		
12. Check Ap	propriate Box to Indic	ate Nature of Notice	, Report or Other I	<b>D</b> ata	
NOTICE OF INTI		911	BSEQUENT REP	ODT OE:	
	ENTION TO. PLUG AND ABANDON X			ALTERING CASING	
	CHANGE PLANS		RILLING OPNS.□ I	P AND A	
<del></del>	MULTIPLE COMPL	] CASING/CEME	NT JOB D		
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM					
OTHER:		OTHER:			
13. Describe proposed or complet of starting any proposed work proposed completion or recon	). SEE RULE 19.15.7.14 l				
a. See attached Current and Proposed Well sxs of cement and displace to the perforation					
b. Pull up 1150' and spot 20 sxs of cement	at the base of salt, leaving TO	OC around 950'. WOC, the	en tag to confirm this 2 <sup>nd</sup>	plug. POOH w/ tubing.	
c. Perforate the 4-1/2" casing at 350', just then tag to confirm this 3 <sup>rd</sup> plug.	pelow the surface casing dept	h. Spot 20 sxs and squeeze	e, leaving TOC inside of	4-1/2" around 150'. WOC,	
d. Spot cement plug from 60' back to the s	urface and ensure that there is	s also cement in the 4-1/2"	x 8-5/8" annuls.		
e. Install the dry hole marker and clean the	location. Submit the Subseq	uent Report of Sundry Noti	ice for the well abandonn	nent activities.	
f. Perform the sire restoration and reclamate CONDITIONS OF APPROVAL AT TACHED	ion activities.	Approved for pluggin	g of well bore only. Is retained pending receipt to Report of Well Plugging)	OIL CONSERVATION	
approval Granted providing work is	Rig Rele	which may be found	at OCD Web Page under	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Completed by		Form, www.cmnrd.st	ate.nm.us/ocd.	OCT 2 3 2014	
10/28/2015				·	
	s true and complete to	the best of my knowled	lge and belief.	RECEIVED	
SIGNATURE Claud D. Rich	TITLE	Operations Manager	DAT	E 10/20/14	
Type or print name Claud D. Riddles For State Use Only	E-mail :	address: <u>criddles@plater</u>	nergy.com PHO	NE: 713.364.7822	
APPROVED BY WOOD	LTITLE_	DSTELSpen	DAT_DAT	TE 105/85/01	
Conditions of Approval (if any):	1 1 1111			, , , , , , , , , , , , , , , , , , ,	
* See Attac	hed CUA.	\$			

# Tandem Energy Corporation Old Loco Unit No. 021 (API 30-015-23651)


Grayburg-Jackson; SR-Q-G-SA Eddy County, New Mexico Current Wellbore



## Tandem Energy Corporation

#### Old Loco Unit No. 021 (API 30-015-23651)

Grayburg-Jackson; SR-Q-G-SA Eddy County, New Mexico Proposed Wellbore



## NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

### CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Tande	en Energy
Well Name & Number:_	Old Soco Unit #21
200	15-23651

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 1 year of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.

11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 10/28/2014

APPROVED BY;

#### GUIDELINES FOR PLUGGING AND ABANDONMENT

#### DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - o Fusselman
  - o Devonian
  - o Morrow
  - o Wolfcamp
  - o Bone Spring
  - o Delaware
  - Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).