Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

# 5. Lease Serial No. NMLC054988B

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allot	tee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/A	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well				8. Well Name and No. JENKINS B FEDERAL 10	
			:-	9. API Well No.	
COG OPERATING LLC E-Mail: kcastillo@concho.com			30-015-30668-00-S1		
3a. Address ONE CONCHO CENTER 600 W MIDLAND, TX 79701	Phone No. (include area code): 432-685-4332		10. Field and Pool, or Exploratory LOCO HILLS-PADDOCK		
4. Location of Well. (Footage, Sec., T., R.,		11. County or Par	11. County or Parish, and State		
Sec 20 T17S R30E NENW 850FNL 2310FWL			EDDY COUNTY, NM		
12. CHECK APPROP	RIATE BOX(ES) TO INI	DICATE NATURE OF N	OTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent [	☐ Acidize	□ Deepen	☐ Production (Start/Resumo	e)   Water Shut-Off	
Subsequent Penart	Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity	
	☐ Casing Repair	☐ New Construction	■ Recomplete	☐ Other	
	Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon		
	Convert to Injection	Plug Back	☐ Water Disposal		
determined that the site is ready for final in COG Operating LLC respectfully record well type from injection to oil produce we are going to set a CIBP at 435 have our PBTD @ 4310?. We plat 200?-300? of rathole below our betubing from getting stuck with sand the option to re-enter the Glorietta Procedures:  Rod Pull Procedure	equests to recomplete this ucer.  50? (68? above our YESO in to have our bottom perfs to give our bot d. In addition to having de later times.	perfs) w/ 40 of CMT on t s from 3997-4133?. Ideall tom hole assembly room esired rathole space, this	op of the plug to y, we like to have and prevent gives COG	TED FOR APPROVAL IS OF APPROVAL M OIL CONSERVATION ARTESIA DISTRICT	
14. I hereby certify that the foregoing is true	and correct. ectronic Submission #2837	37 verified by the BLM We	Unformation System		
For COG OPERATING L Committed to AFMSS for processing by JEN Name (Printed/Typed) KANICIA CASTILLO		ATING LLC. sent to the Ca	arlsbad 12/02/2014 (15JAM0107SE)	RECEIVED	
Signature (Electronic Submission)		Date 12/02/2	Date 12/02/2014 APPROVFD		
	THIS SPACE FOR F	EDERAL OR STATE	OFFICE USE		
Approved By		Title	//OEC 2/20	)14 Da	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		ect lease Office	BUREAU OF LAND MAN		
Title 18 U.S.C. Section 1001 and Title 43 U.S. States any false, fictitious or fraudulent states	C. Section 1212, make it a crimments or representations as to ar	e for any person knowingly and ny matter within its jurisdiction.	wilfully to make to any departme	nt or agency of he United	

#### Additional data for EC transaction #283737 that would not fit on the form

#### 32. Additional remarks, continued

- ? MIRU WSU, NU BOP
- ? Unset packer and POOH with tubing ? PU scraper and scrape down to 4370?
- ? POOH with tubing LD
- ? RU Wireline
- ? Set CIBP @ 4350? ? Wireline truck dump 40? Class C cement of top of CIBP
- ? Tag cement plug to verify depth of 4310?
- ? Pull up 4? to circulate hole clean with fresh water, and displace w/ 2% KCL and 1% packer corrosion inhibitor.
- ? Test Casing to 4,200 psi and report back to engineering if the pressure holds.
- ? Secure wellbore ? RDMO WSU

- Tentative Recompletion Procedure ? NU frac valve, and test casing to 4200 psi
- ? Rig up wireline.
- ? RIH w/ perforating guns and perforate San Andres Zone from 3997'-4133' w/ 3 spf, 60? phasing, 54 holes.

- Acidize w/ 1500 gals of 15% HCl. Frac zone w/ 181,250 # of sand. Record ISIP and FG, Get 5, 10, 15 min SIP

- ? Rig up Wireline
  ? RiH w/ WL and set Composite Plug @ 3900?
  ? Perforate San Andres Zone from 3698'-3843' w/ 3 spf, 60? phasing, 54 holes.
  ? Acidize w/ 1500 gals of 15% HCl.
  ? Frac zone w/ 181,250 # of sand.

- ? Record ISIP and FG, Get 5, 10, 15 min SIP ? MIRU WSU ? Rig up Wireline

- ? Rig up Wireline
  ? RiH w/ WL and set Composite Plug @ 3600?
  ? Perforate San Andres Zone from 3076'-3268' w/ 3 spf, 60? phasing, 54 holes.
  ? Acidize w/ 1500 gals of 15% HCI.
  ? Frac zone w/ 181,250 # of sand.
  ? Record ISIP and FG, Get 5, 10, 15 min SIP
  ? RIH with Production tbg and tag for fill w/ bailer at knocked Composite plugs @ 3600? and 3900?
  ? Clean out fill to new PBTD @ 4310?
  ? POOH bailer and tbg
  ? RIH with production tubing and locate intake at 4150?
  ? Set TAC @ 3050?

- Set TAC @ 3050?
- ? RIH w/ rods and pump. ? RDMO rig.

# COG Operating LLC

#### Lease & Well #

Jenkins B Federal # 10 WIW

Sec 20C 17S 30E, Eddy Co., NM

SPUD: 8/3/99 3001530668

Elevation - 3649

KB -

13.3/8" 48# K-55 STC csg @ 417', 400 sx. Circ 85 sx.

8 5/8" 32# 8rd J-55 STC @ 1037, 475 sx, circ. 84 sx

DV tool -3838'

Marker jt @ 4370'

138 jts PL 2 7/8" tbg

PL SN

Arrowset PL pkr @ 4370'

Converted to WIW 8-22-07

Yeso

4418 - 4665.5, 73 holes

Acidized w/2,500 gal 15% HCL

Trt w/32,000 gal 20% HCL, 54,000 gal LG, 5,000 gal 15% HCL

PBTD - 4703'

1st stage: 200 sx 50/50, circulated 85 sx. 2nd stage: 800 sx, circulated 60 sx.

5 1/2" 17# J-55 LT&C csg @ 4714'.

# **COG Operating LLC**

Lease & Well #

Jenkins B Federal # 10

Sec 20C 17S 30E, Eddy Co., NM

SPUD: 8/3/99 3001530668

Elevation - 3649

. КВ -

🕯 13 3/8" 48# K-55 STC csg @ 417', 400 sx. Circ 85 sx.

8 5/8" 32# 8rd J-55 STC @ 1037, 475 sx, circ. 84 sx

3076'-3268', 181,250# of proppant and 1500 gallons of HCL Acid

3698'-3843', 181,250# of proppant and 1500 gallons of HCL Acid

3997'-4133', 181,250# of proppant and 1500 gallons of HCL Acid

CIBP at 4350' w/ 40' of CMT to 4310'

Marker jt @ 4370

DV tool -3838<sup>1</sup>

Yeso

4418 - 4665.5, 73 holes

Acidized w/2,500 gal 15% HCL

Trt w/32,000 gal 20% HCL, 54,000 gal LG, 5,000 gal 15% HCL

1st stage: 200 sx 50/50, circulated 85 sx. 2nd stage: 800 sx, circulated 60 sx. 5 1/2" 17# J-55 LT&C csg @ 4714'.

PBTD - 4703'

Jenkins B Federal 30-015-30668
COG Operating, LLC.
December 02, 2014
Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by March 02, 2015.

1. Operator shall set a CIBP at 4,350' and place 40' Class C cement on top. Tag required.

Note: At a later date, more cement will be required on top of the CIBP when the Glorieta is abandoned.

- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a **2000 (2M)** BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 9 Subsequent sundry required detailing work done and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
- 10. See attached for general requirements.

JAM 120214

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### **General Requirements for Plug Backs**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety** (90) days from this approval.

If you are unable to plug back the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.