

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	8. Well Name and No. JENKINS B FEDERAL 14
2. Name of Operator COG OPERATING LLC Contact: KANICIA CASTILLO E-Mail: kcastillo@concho.com	9. API Well No. 30-015-32257-00-S1
3a. Address ONE CONCHO CENTER 600 W ILLINOIS AVENUE MIDLAND, TX 79701	10. Field and Pool, or Exploratory LOCO HILLS-PADDOCK
3b. Phone No. (include area code) Ph: 432-685-4332	11. County or Parish, and State EDDY COUNTY, NM
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 20 T17S R30E NWNW 745FNL 990FWL	

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Deepen
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Alter Casing
	<input type="checkbox"/> Fracture Treat
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Change Plans
	<input type="checkbox"/> Plug and Abandon
	<input type="checkbox"/> Convert to Injection
	<input type="checkbox"/> Plug Back
	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Reclamation
	<input checked="" type="checkbox"/> Recomplete
	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Well Integrity
	<input type="checkbox"/> Other
	<input type="checkbox"/> Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

COG Operating LLC respectfully requests to recomplete this well to the San Andres and change the well type from injection to oil producer.

We are going to set a CIBP at ~~4225~~ ⁴²⁰⁰ (25' above the YESO perms) w/ 40 of CMT on top of the plug to have our PBTD @ 4185'. We plan to have our bottom perms from 3962'-4104'. Ideally, we like to have 200'-300' of rathole below our bottom perms to give our bottom hole assembly room and prevent tubing from getting stuck with sand. In addition to having desired rathole space, this gives COG the option to re-enter the Glorietta/Yeso formation at later time.

Procedures:

Rod Pull Procedure

*Accepted for record
NMOCDC 12/19/14
Submit C102 JRS*

**SEE ATTACHED FOR
CONDITIONS OF APPROVAL**
NM OIL CONSERVATION
ARTESIA DISTRICT
DEC 09 2014

14. I hereby certify that the foregoing is true and correct.		Electronic Submission #283731 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Carlsbad Committed to AFMSS for processing by JENNIFER MASON on 12/02/2014 (15JAM0106SE)		RECEIVED
Name (Printed/Typed)	KANICIA CASTILLO	Title	PREPARER	
Signature	(Electronic Submission)	Date	12/02/2014	

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By	Title	Date
		DEC 2 2014
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any statement or representation to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #283731 that would not fit on the form

32. Additional remarks, continued

- ? MIRU WSU, NU BOP
- ? POOH w/ rods and pump on LD on location
- o Let Engineering know the quantity and conditions of the rods and pump
- ? RU Wireline
- ? Set CIBP @ 4225? ⁴²⁰⁰
- ? Wireline truck dump 40? Class C cement of top of CIBP
- ? Tag cement plug to verify depth of 4185?
- ? Pull up 4? to circulate hole clean with fresh water, and displace w/ 2% KCL and 1% packer corrosion inhibitor.
- ? Test Casing to 4,200 psi and report back to engineering if the pressure holds.
- ? Secure wellbore
- ? RDMO WSU

Tentative Recompletion Procedure

- ? NU frac valve, and test casing to 4200 psi
- ? Rig up wireline.
- ? RIH w/ perforating guns and perforate San Andres Zone from 3962?-4104? w/ 3 spf, 60? phasing, 54 holes.
- ? Acidize w/ 1500 gals of 15% HCl.
- ? Frac zone w/ 181,250 # of sand.
- ? Record ISIP and FG, Get 5, 10, 15 min SIP
- ? Rig up Wireline
- ? RIH w/ WL and set Composite Plug @ 3900?
- ? Perforate San Andres Zone from 3679'-3859' w/ 3 spf, 60? phasing, 54 holes.
- ? Acidize w/ 1500 gals of 15% HCl.
- ? Frac zone w/ 181,250 # of sand.
- ? Record ISIP and FG, Get 5, 10, 15 min SIP
- ? MIRU WSU
- ? Rig up Wireline
- ? RIH w/ WL and set Composite Plug @ 3600?
- ? Perforate San Andres Zone from 3058'-3239' w/ 3 spf, 60? phasing, 54 holes.
- ? Acidize w/ 1500 gals of 15% HCl.
- ? Frac zone w/ 181,250 # of sand.
- ? Record ISIP and FG, Get 5, 10, 15 min SIP
- ? RIH with Production tbg and tag for fill w/ bailer at knocked Composite plugs @ 3600? and 3900?
- ? Clean out fill to new PBDT @ 4185?
- ? POOH bailer and tbg
- ? RIH with production tubing and locate intake at 4125?.
- ? Set TAC @ 3050?
- ? RIH w/ rods and pump.
- ? RDMO rig.

COG Operating LLC

Lease & Well #


Jenkins B Federal # 14 WIW

SPUD: 6/9/02
3001532257

Sec 20D, 17S, 30E, Eddy Co., NM

Elevation - 3639

KB -



COG Operating LLC

Lease & Well #


Jenkins B Federal # 14 WIW

SPUD: 6/9/02
3001532257

Sec 20D, 17S, 30E, Eddy Co., NM

Elevation - 3639

KB -



**Jenkins B Federal 14
30-015-32257
COG Operating, LLC.
December 02, 2014
Conditions of Approval**

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by March 02, 2015.

- 1. Operator shall set a CIBP at 4,200' and place 40' Class C cement on top. Tag required.**

Note: At a later date, more cement will be required on top of the CIBP when the Glorieta is abandoned.

- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.**
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.**
- 4. Surface disturbance beyond the originally approved pad must have prior approval.**
- 5. Closed loop system required.**
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.**
- 7. Operator to have H2S monitoring equipment on location.**
- 8. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.**

9. **Subsequent sundry required detailing work done and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.**

10. **See attached for general requirements.**

JAM 120214

BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street,
Carlsbad, New Mexico 88220
575-234-5972

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety (90)** days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

2. **Notification:** Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.

3. **Blowout Preventers:** A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. **Mud Requirement:** Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. **Cement Requirement:** Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement.

Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

6. **Subsequent Plug back Reporting:** Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date work was completed.**

7. **Trash:** All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.