

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JAN 27 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1502840360

OPERATOR

Initial Report Final Report

Name of Company	Bumett Oil Co., Inc. <i>3080</i>	Contact	Leslie Garvis
Address	801 Cherry Street - Suite 1500, Ft. Worth, TX 76102	Telephone No.	817-583-8730
Facility Name	Gissler B 3-3 Tank Battery	Facility Type	Tank Battery
Surface Owner	BLM	Mineral Owner	BLM
		API No.	Lease # BLM/VW-2748

LOCATION OF RELEASE

30-015-25221

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	11	17S	30E	441'	South	467'	West	Eddy

Latitude *32.84360* Longitude *103.949126*

NATURE OF RELEASE

175 bbl/oil 175 bbl/PW

Type of Release	Fire	Volume of Release	approx: 350 bbls	Volume Recovered	None - burned
Source of Release	Heater Treater Fire	Date and Hour of Occurrence	1/19/15	Date and Hour of Discovery	1/19/15 1716 MST
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM - J. Amos; OCD - H. Patterson (By Voice Mail and Email)		
By Whom?	Leslie Garvis	Date and Hour	1/19/15 approx 1800 MST		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The fire is believed to have started in the main production heater treater and spread to the other heaters and separators. No tanks were involved. Flowlines were also destroyed. There was a release of approximate 350 bbls of liquid (combination of oil and water) but there is no way for us to determine the amounts of each as the fluid burned during the fire.

Describe Area Affected and Cleanup Action Taken.*

Soil samples have been taken. Approximately 2' of material will be removed and hauled to disposal. Once the material has been removed, the pad will be rebuilt with a 20 mil liner installed. The remaining impact will be left in place, and will be addressed after the battery has been rebuilt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie Garvis</i>	OIL CONSERVATION DIVISION	
Printed Name: Leslie Garvis	Approved by Environmental Specialist: <i>H. Patterson</i>	
Title: Regulatory Coordinator	Approval Date: <i>1/28/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: lgarvis@bumettoil.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines attached <input type="checkbox"/>	
Date: 1/27/15	Phone: 817-583-8730	SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: *2/28/15*

* Attach Additional Sheets If Necessary

2RP-2763