Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
Office District 1 – (575) 393-(14) OIL CONSERVATO 1625 N. French Dr., Hobbs, NA 382-51 A DISTRICT	Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 A DISTRICT		WELL API NO. 30-005-61392
District II – (575) 748-1283 811 S. First St., Artesia, NM 8821 AN 1 2 2015	L CONSERVATION DIVISION	5. Indicate Type of Lease
	1220 South St. Francis Dr.	STATE STEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NECEIVED		LG-569
8/303	DEDODES ON WELLS	
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR PROPOSALS TO D		7. Lease Name or Unit Agreement Name Skink SK State
DIFFERENT RESERVOIR. USE "APPLICATION FO		8. Well Number
PROPOSALS.)		
1. Type of Well: Oil Well Gas Well	Other P&A	2
2. Name of Operator		9. OGRID Number
Yates Petroleum Corporation	<u> </u>	025575 10. Pool name or Wildcat
3. Address of Operator		Pecos Slope; Abo
105 South Fourth Street, Artesia, NM 88210	<u></u>	recos Siope, Abo
4. Well Location		1000 C 4 C 4 L W 4 L
Unit Letter N : 660 fe	eet from the South line and	1980 feet from the West line
Section 36 T	ownship 7S Range 25E	NMPM Chaves County
11. Elev	vation (Show whether DR, RKB, RT, GR, etc.	c.)
	3609'GR	
12. Check Appropri	ate Box to Indicate Nature of Notice	Report or Other Data
12. Officer appropri	ate Don to indicate i tassie of i toste.	, report of outer zum
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A		
PULL OR ALTER CASING	PLE COMPL   CASING/CEME	NT JOB
DOWNHOLE COMMINGLE		GAR OF TOMES THERE IN THE
CLOSED-LOOP SYSTEM		
OTHER: (A) (Phi phi a) A (A) (A) (A) (A)	OTHER:	<u></u>
13. Describe proposed or completed oper	ations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
of starting any proposed work). SEE	RULE 19.15.7.14 NMAC. For Multiple C	
	RULE 19.15.7.14 NMAC. For Multiple C	
of starting any proposed work). SEE proposed completion or recompletion	RULE 19.15.7.14 NMAC. For Multiple C	ompletions: Attach wellbore diagram of
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP.	RULE 19.15.7.14 NMAC. For Multiple C n. RIH with GR/JB to 3800'. Set a 4-1/2" CII	ompletions: Attach wellbore diagram of Attach wellbore diagram of BP at 3798'. Tagged CIBP.
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25	RULE 19.15.7.14 NMAC. For Multiple C n. "RIH with GR/JB to 3800'. Set a 4-1/2" CII 5 sx Class "C" Neat cement on top of CIBP.	ompletions: Attach wellbore diagram of
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa	RULE 19.15.7.14 NMAC. For Multiple C n. "RIH with GR/JB to 3800'. Set a 4-1/2" CII 5 sx Class "C" Neat cement on top of CIBP. ced TOC to 1300'. WOC 4 hrs. Tagged at	ompletions: Attach wellbore diagram of BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'.
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke	RIH with GR/JB to 3800°. Set a 4-1/2° CII 5 sx Class "C" Neat cement on top of CIBP. ced TOC to 1300°. WOC 4 hrs. Tagged at circulation out 10-3/4° x 4-1/2°. Pumped 4	ompletions: Attach wellbore diagram of
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 holes	RIH with GR/JB to 3800°. Set a 4-1/2° CII 5 sx Class "C" Neat cement on top of CIBP. ced TOC to 1300°. WOC 4 hrs. Tagged at circulation out 10-3/4° x 4-1/2°. Pumped 4	ompletions: Attach wellbore diagram of
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 holesaing.	RULE 19.15.7.14 NMAC. For Multiple Con.  RIH with GR/JB to 3800'. Set a 4-1/2" CIR S sx Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce	ompletions: Attach wellbore diagram of BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 holes	RULE 19.15.7.14 NMAC. For Multiple Con.  RIH with GR/JB to 3800'. Set a 4-1/2" CIR S sx Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce	ompletions: Attach wellbore diagram of BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 holesaing.	RULE 19.15.7.14 NMAC. For Multiple Con.  RIH with GR/JB to 3800'. Set a 4-1/2" CIR S sx Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce	ompletions: Attach wellbore diagram of  BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 holesaing.	RULE 19.15.7.14 NMAC. For Multiple Con.  RIH with GR/JB to 3800'. Set a 4-1/2" CIR S sx Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce	Ompletions: Attach wellbore diagram of BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well hore onic
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 holesaing.	RIH with GR/JB to 3800'. Set a 4-1/2" CII 5 sx Class "C" Neat cement on top of CIBP. ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W	BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Placeting)
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 holesaing.	RULE 19.15.7.14 NMAC. For Multiple Con.  RIH with GR/JB to 3800'. Set a 4-1/2" CIR S sx Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce	BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 holesaing.	RIH with GR/JB to 3800'. Set a 4-1/2" CII 5 sx Class "C" Neat cement on top of CIBP. ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W	BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Placeting)
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 holesaing.	RIH with GR/JB to 3800'. Set a 4-1/2" CII 5 sx Class "C" Neat cement on top of CIBP. ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W	BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 holesaing.	RIH with GR/JB to 3800'. Set a 4-1/2" CII 5 sx Class "C" Neat cement on top of CIBP. ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W	BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing. 1/7/15 – Dug out cellar and cut off wellhead.	RIH with GR/JB to 3800°. Set a 4-1/2" CII 5 sx Class "C" Neat cement on top of CIBP. ced TOC to 1300°. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60°. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W	BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing. 1/7/15 – Dug out cellar and cut off wellhead.	RIH with GR/JB to 3800°. Set a 4-1/2" CII 5 sx Class "C" Neat cement on top of CIBP. ced TOC to 1300°. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60°. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W	BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
of starting any proposed work). SEE proposed completion or recompletion  12/19/14 – Pumped 40 bbls brine. NU BOP.  12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing.  1/7/15 – Dug out cellar and cut off wellhead.	RULE 19.15.7.14 NMAC. For Multiple Co.  RIH with GR/JB to 3800'. Set a 4-1/2" CIR Sex Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W	BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well hore onto. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
of starting any proposed work). SEE proposed completion or recompletion 12/19/14 – Pumped 40 bbls brine. NU BOP. 12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing. 1/7/15 – Dug out cellar and cut off wellhead.	RULE 19.15.7.14 NMAC. For Multiple Co.  RIH with GR/JB to 3800'. Set a 4-1/2" CIR Sex Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W	BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well hore onto. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
of starting any proposed work). SEE proposed completion or recompletion  12/19/14 – Pumped 40 bbls brine. NU BOP.  12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing.  1/7/15 – Dug out cellar and cut off wellhead.	RULE 19.15.7.14 NMAC. For Multiple Co.  RIH with GR/JB to 3800'. Set a 4-1/2" CIR Sex Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W	BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well hore onto. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
of starting any proposed work). SEE proposed completion or recompletion  12/19/14 – Pumped 40 bbls brine. NU BOP.  12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing.  1/7/15 – Dug out cellar and cut off wellhead.	RIH with GR/JB to 3800'. Set a 4-1/2" CII 5 sx Class "C" Neat cement on top of CIBP. ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W  Rig Release Date:	BP at 3798'. Tagged CIBP. Perforated 4 holes at 1570'. Pumped 30 sx 1103'. 0 sx Class "C" Neat cement. Displaced to 800'. ment and circulated to surface. Topped out  ELL IS PLUGGED AND ABANDONED.  Approved for plugging of well hore onto. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
of starting any proposed work). SEE proposed completion or recompletion  12/19/14 – Pumped 40 bbls brine. NU BOP.  12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing.  1/7/15 – Dug out cellar and cut off wellhead.  Spud Date:  I hereby certify that the information above is the start of	RIH with GR/JB to 3800'. Set a 4-1/2" CII S xx Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. WY COLOR Rig Release Date:  Rig Release Date:  TITLE Regulatory Reporting	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.st.ate.nm.us/oed.  Supervisor DATE January 9, 2015
of starting any proposed work). SEE proposed completion or recompletion  12/19/14 - Pumped 40 bbls brine. NU BOP.  12/20/14 - Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 - Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing.  1/7/15 - Dug out cellar and cut off wellhead.  Spud Date:  I hereby certify that the information above is to sign and cut of the sign and cut o	RIH with GR/JB to 3800'. Set a 4-1/2" CII 5 sx Class "C" Neat cement on top of CIBP. ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W  Rig Release Date:	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.st.ate.nm.us/oed.  Supervisor DATE January 9, 2015
of starting any proposed work). SEE proposed completion or recompletion  12/19/14 – Pumped 40 bbls brine. NU BOP.  12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing.  1/7/15 – Dug out cellar and cut off wellhead.  Spud Date:  I hereby certify that the information above is the start of	RIH with GR/JB to 3800'. Set a 4-1/2" CII S xx Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. WY COLOR Rig Release Date:  Rig Release Date:  TITLE Regulatory Reporting	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.st.ate.nm.us/oed.  Supervisor DATE January 9, 2015
of starting any proposed work). SEE proposed completion or recompletion  12/19/14 - Pumped 40 bbls brine. NU BOP.  12/20/14 - Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 - Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing.  1/7/15 - Dug out cellar and cut off wellhead.  Spud Date:  Type or print name	RIH with GR/JB to 3800'. Set a 4-1/2" CII S sx Class "C" Neat cement on top of CIBP. ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W  Rig Release Date:  Rig Release Date:  TITLE Regulatory Reporting  E-mail address: tinah@yatespetrole	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.st.ate.nm.us/ocd.  Supervisor DATE January 9, 2015  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.st.ate.nm.us/ocd.
of starting any proposed work). SEE proposed completion or recompletion  12/19/14 – Pumped 40 bbls brine. NU BOP.  12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing.  1/7/15 – Dug out cellar and cut off wellhead.  Spud Date:  Type or print name	RIH with GR/JB to 3800'. Set a 4-1/2" CII S xx Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. WY COLOR Rig Release Date:  Rig Release Date:  TITLE Regulatory Reporting	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.st.ate.nm.us/oed.  Supervisor DATE January 9, 2015
of starting any proposed work). SEE proposed completion or recompletion  12/19/14 - Pumped 40 bbls brine. NU BOP.  12/20/14 - Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 - Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing.  1/7/15 - Dug out cellar and cut off wellhead.  Spud Date:  Type or print name	RIH with GR/JB to 3800'. Set a 4-1/2" CIT is sx Class "C" Neat cement on top of CIBP. Ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. We have complete to the best of my knowled to the complete to the best of my knowled.  Rig Release Date:  TITLE Regulatory Reporting  E-mail address: tinah@yatespetrole	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.st.ate.nm.us/ocd.  Supervisor DATE January 9, 2015  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.st.ate.nm.us/ocd.
of starting any proposed work). SEE proposed completion or recompletion  12/19/14 – Pumped 40 bbls brine. NU BOP.  12/20/14 – Loaded hole with mud. Spotted 25 Class "C" Neat cement, Glorieta plug. Displa 12/21/14 – Perforated 4 holes at 900'. Broke WOC 4 hrs. Tagged at 760'. Perforated 4 hole casing.  1/7/15 – Dug out cellar and cut off wellhead.  Spud Date:  Type or print name	RIH with GR/JB to 3800'. Set a 4-1/2" CII S sx Class "C" Neat cement on top of CIBP. ced TOC to 1300'. WOC 4 hrs. Tagged at circulation out 10-3/4" x 4-1/2". Pumped 4 les at 60'. Pumped 60 sx Class "C" Neat ce Installed dry hole marker. Filled cellar. W  Rig Release Date:  Rig Release Date:  TITLE Regulatory Reporting  E-mail address: tinah@yatespetrole	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.st.ate.nm.us/ocd.  Supervisor DATE January 9, 2015  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.st.ate.nm.us/ocd.