

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAR 03 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NAB1506439255

OPERATOR

Initial Report Final Report

Name of Company <i>Devon Energy Production</i> <i>6137</i>	Contact <i>Rudy Zuniga</i>
Address <i>6488 Seven Rivers Hwy Artesia, NM 88220</i>	Telephone No. <i>575-390-5435</i>
Facility Name <i>Rigel 20 Fed Com 1H</i>	Facility Type <i>Oil</i>

Surface Owner <i>Federal</i>	Mineral Owner <i>Federal</i>	API No. <i>30-015-39393</i>
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	20	19S	31E	425	North	330	West	Eddy

Latitude: N 32.6519959

Longitude: W 103.8989484

NATURE OF RELEASE

Type of Release <i>Oil Spill in to containment</i>	Volume of Release <i>30 bbls</i>	Volume Recovered <i>30 bbls</i>
Source of Release <i>Casing and Flow line valve was left open at the Rigel 20 Fed Com 5H</i>	Date and Hour of Occurrence <i>January 27, 2015 @ 1:55 am</i>	Date and Hour of Discovery <i>January 27, 2015 @ 1:55 am</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>BLM Jim Amos @ 8:30 am OCD Mike Bratcher @ 8:35 am</i>	
By Whom? <i>Ray Carter</i>	Date and Hour <i>January 28, 2015 @ 8:30 and 8:35</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Legend Energy Services pumped 1700 bbls of water down the hole at the Rigel Fed Com 5H and the gate valve was left open which caused the Rigel 20 Fed Com 1H battery to swanp the 2 phase separator and heater, causing water and oil to flow into tank #1 at a high rate. 30 bbls of oil was spilled into containment and 30 bbls of oil was recovered. Valve was closed to stop the over flow.

Describe Area Affected and Cleanup Action Taken.*
The oil spill was in containment, it was 30 bbls and 30 bbls was recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Corina Moya</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>Field Admin Support</i>	Approval Date: <i>3/5/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>corina.moya@dvn.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: <i>1/28/2015</i>	Phone: <i>575.746.5559</i>	

* Attach Additional Sheets If Necessary

2RP-2854