

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB151064072Z OPERATOR Initial Report Final Report

Name of Company Fair Oil, Ltd. 05531	Contact Rodney K. Thomson
Address P.O. Box 689, Tyler Tx 75710	Telephone No. 903-510-6527
Facility Name Fair 17 Federal #2	Facility Type Oil Production Tank Battery

Surface Owner BLM	Mineral Owner BLM	API No. 30-015-41763
-------------------	-------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	17	17S	31E	1792	North	727	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil	Volume of Release 42 bbls	Volume Recovered 40 bbls
Source of Release Tank Battery	Date and Hour of Occurrence 11-17-14 6:30 am	Date and Hour of Discovery 11-17-14 6:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Rodney K. Thomson	Date and Hour 1-18-14	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT


DEC 08 2014

Describe Cause of Problem and Remedial Action Taken.*
Hammer Union was disconnected and valve to tank left open while filling tank.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*
Disconnected hammer union and open valve on tank caused spill when filling storage tank. All spilled oil was contained within the firewall of the tank battery. 40 bbls of the 42 bbls spilled was recovered. Contaminated material within firewall was removed and hauled to disposal site. Fresh material was placed within the firewall. Cleanup completed on 11-18-14.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Rodney K. Thomson	Accepted for record NMOCD	
Title: Production Manager	Approval Date: 11/16/14	Expiration Date: N/A
E-mail Address: production@fairoil.com	Conditions of Approval: Analytical	Attached <input type="checkbox"/>
Date: 12-4-14 Phone: 903-510-6527	(Data Required) For Closure	

* Attach Additional Sheets If Necessary

2RP-2955