
	•			
Submit 1 Copy 10 Appropriate District	State of New Me	exico	Form C-1	03
District I - (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 20)13
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	J DIVISION	30-015-32118	
<u>District III</u> - (505) 334-6178	1220 South St. Fra	ncis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 8		STATE X FEE 6. State Oil & Gas Lease No.	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	20110 20, 10110		VA-1541	
		UG BACK TO A	7. Lease Name or Unit Agreement Name Little Box State	;
PROPOSALS.) 1. Type of Well: Oil Well Gas	Well X Other		8. Well Number #6	
2. Name of Operator Nadel and Gussm	an Permian, LLC		9. OGRID Number 155615	
 Address of Operator 601 N. Marienfeld, Suite 508, Midland, 	TX 79701		10. Pool name or Wildcat Little Box Canyon (Morrow)	
4. Well Location		1. 1000 0		
	00 feet from the South_line a			
Section 36	Township 20S	Range 21		
11.	Elevation (Show whether DR	, κκ <i>b</i> , κ1, GR, etc	n and an appendix of the part of a	di se
12. Check Appro	opriate Box to Indicate N	lature of Notice	, Report or Other Data	
NOTICE OF INTER	ITION TO:	SUE	BSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK 🗌 🛛 PL	UG AND ABANDON 🔲	REMEDIAL WOR	RK 🔲 ALTERING CASING	
	IANGE PLANS			
	ILTIPLE COMPL	CASING/CEMEN	NT JOB	
CLOSED-LOOP SYSTEM		OTHER:	Г	٦.
	SEE RULE 19.15.7.14 NMA		nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
 Nadel and Gussman Permian, LLC hereby MIRU pulling unit, install BOP' Set CIBP @ +/- 8,002' and dump GBIH with production tubing an Perform mechanical integrity press Leave well temporarily abandom 	s, and pull production tubing p bail 35' of cement on top of d circulate well with fresh wa essure test on casing and obtai	CIBP. Note that to ter containing 1%	op existing perforation is at 8,052'.	
		•		
		[
Spud Date:	Rig Release D	ate:		
	· · · · · · · · · · · · · · · · · · ·			
I hereby certify that the information above	e is true and complete to the t	best of my knowled	ge and belief.	
SIGNATURE Joel Martin				
TITLEEngineer	DATE	4/23/2015		
Type or print name _Joel Martin	E-mail address:		PHONE:	
For State Use Only APPROVED BY: Approved (for a p)	IL TITLE DIST	r HSqX	WISO DATE 4/23/20	15
Conditions of Approval (if any):	nhi		1 1	
> see Attached (ノガン			

NADEL AND GUSSMAN PERMIAN



APPROVED TEMPORARY ABANDONMENT

19.15.25.11 REPORTS FOR PLUGGING AND ABANDOMENT: A. The operator shall file form C-105 as provided in 19.15.7.16 NMAC. B. Within 30 days after completing required restoration work, the operator shall file with the division a record of the work done on form C-103 as provided in 19.15.7.14 NMAC. C. The division shall not approve the record of plugging or release a bond until the operator has filed necessary reports and the division has inspected and approved the location. [19.15.25.11 NMAC -Rp, 19.15.4.202 NMAC, 12/1/08] 19.15.25.12 APPROVED TEMPORARY ABANDONMENT: The division may place a well in approved temporary abandonment for a period of up to five years. Prior to the expiration of an approved temporary abandonment the operator shall return the well to beneficial use under a plan the division approves, permanently plug and abandon the well and restore and remediate the location or apply for a new approval to temporarily abandon the well. [19.15.25.12 NMAC - Rp, 19.15.4.203 NMAC, 12/1/08] 19.15.25.13 REQUEST FOR APPROVAL AND PERMIT FOR APPROVED TEMPORARY ABANDONMENT: A. An operator seeking approval for approved temporary abandonment shall submit on form C-103 a notice of intent to seek approved temporary abandonment for the well describing the proposed temporary abandonment procedure the operator will use. The operator shall not commence work until the division has approved the request. The operator shall give 24 hours notice to the appropriate division district office before beginning work. B. The division shall not approve temporary abandonment until the operator furnishes evidence demonstrating that the well's casing and cementing are mechanically and physically sound and in such condition as to prevent: (1) damage to the producing zone; (2) migration of hydrocarbons or water; (3) the contamination of fresh water or other natural resources; and (4) the leakage of a substance at the surface. C. The operator shall demonstrate both internal and external mechanical integrity pursuant to Subsection A of 19.15.25.14 NMAC. D. Upon successful completion of the work on the temporarily abandoned well, the operator shall submit a request for approved temporary abandonment to the appropriate division district office on form C-103 together with other information Subsection E of 19.15.7.14 NMAC requires. E. The division shall specify the permit's expiration date, which shall be not more than five years from the date of approval. [19.15.25.13 NMAC - Rp, 19.15.4.203 NMAC, 12/1/08] 19.15.25.14 DEMONSTRATING MECHANICAL INTEGRITY: A. An operator may use the following methods of demonstrating internal casing integrity for wells to be placed in approved temporary abandonment: (1) the operator may set a cast iron bridge plug within 100 feet of uppermost perforations or production casing shoe, load the casing with inert fluid and pressure test to 500 psi surface pressure with a pressure drop of not more than 10 percent over a 30 minute period; (2) the operator may run a retrievable bridge plug or packer to within 100 feet of uppermost perforations or production casing shoe, and test the well to 500 psi surface pressure for 30 minutes with a pressure drop of not greater than 10 percent over a 30 minute period; or (3) the operator may demonstrate that the well has been completed for less than five years and has not been connected to a pipeline. B. During the testing described in Paragraphs (1) and (2) of Subsection A of 19.15.25.14 NMAC the operator shall: (1) open all casing valves during the internal pressure tests and report a flow or pressure change occurring immediately before, during or immediately after the 30 minute pressure test; (2) top off the casing with inert fluid prior to leaving the location; (3) report flow during the test in Paragraph (2) of Subsection A of 19.15.25.14 NMAC to the appropriate division district office prior to completion of the temporary abandonment operations; the division may require

remediation of the flow prior to approving the well's temporary abandonment. C. An operator may use any method approved by the EPA in 40 C.F.R. section 146.8(c) to demonstrate external casing and cement 19.15.25 NMAC http://www.nmcpr.state.nm.us/nmac/parts/title19/19.015.0025.htm[3/2/2012 4:12:43 PM] integrity for wells to be placed in approved temporary abandonment. D. The division shall not accept mechanical integrity tests or logs conducted more than 12 months prior to submittal. E. The operator shall record mechanical integrity tests on a chart recorder with a maximum two hour clock and maximum 1000 pound spring, which has been calibrated within the six months prior to conducting the test. Witnesses to the test shall sign the chart. The operator shall submit the chart with form C-103 requesting approved temporary abandonment. F. The division may approve other testing methods the operator proposes if the operator demonstrates that the test satisfies the requirements of Subsection B of 19.15.25.13 NMAC. [19.15.25.14 NMAC - Rp, 19.15.4.203 NMAC, 12/1/08]

Ι

.375