

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

APR 22 2015

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1511729624

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company	Contact	Garry Michael; Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-513-4895
Facility Name	Cotton Draw Unit 172H	Facility Type	Oil Well

Surface Owner	Federal	Mineral Owner	Federal	API No	30-015-42426
---------------	---------	---------------	---------	--------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	1	25S	31E	195	South	1345	East	Eddy

Latitude: N 32° 09' 09.41"

Longitude: W 103° 43' 38.37"

NATURE OF RELEASE

Type of Release	oil release at the LACT Load line	Volume of Release	64BBLS	Volume Recovered	30 BBLS
Source of Release	At the LACT load line	Date and Hour of Occurrence	April 15, 2015 6:45 AM	Date and Hour of Discovery	April 15, 2015 6:45 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher; OCD & Jim Amos; BLM		
By Whom?	David Washington; Assistant Production Foreman	Date and Hour	April 15, 2015 12:40PM & April 17, 2015 3:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.
N/A

Describe Cause of Problem and Remedial Action Taken.*

Truck driver allowed truck to overflow while collecting an oil load from the LACT unit. LACT unit was turned off upon discovery of the release preventing more oil from being released.

Describe Area Affected and Cleanup Action Taken.*

64 BBLS of oil was released. All oil released remained on location. Size of the affected area is approximately 350'x 50'. 30BBLS of oil was recovered via vacuum truck. Affected soil was treated in place by Enviroclean Services.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandy Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: Sandy Farley	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: 4/27/15	Expiration Date: N/A
E-mail Address: sandy.farley@dv.com	Conditions of Approval:	
Date: 4/22/15 Phone: 575.746.5587	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 5/27/15	

Attached ☐

* Attach Additional Sheets If Necessary

2RP-2966