

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

MAY 11 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1513157754

OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production	Contact Rudy Zuniga, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-390-5435
Facility Name Arcturus 18 Fed 5H	Facility Type Oil

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-41802
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	18	19S	31E	845	FNL	250	FEL	Eddy

Latitude: 32.6653332°N

Longitude: 103.9008789°W

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 20bbls	Volume Recovered 20bbls
Source of Release H.F. back pressure valve	Date and Hour of Occurrence May 6, 2015 6:30 AM	Date and Hour of Discovery May 6, 2015 6:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson, BLM Mike Bratcher, OCD	
By Whom? Lynn Smith, Asst. Production Foreman	Date and Hour Jeff Robertson, BLM May 6, 2015 8:57 AM Mike Bratcher, OCD May 6, 2015 8:59 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*

On May 6, 2015 6:30 AM the Lease Operator was contacted and told that the Arcturus 18 Fed 5H was leaking from the well head, upon Lease Operator's arrival to the location he discovered a H. F. back pressure valve had washed out releasing 20bbls of oil and produced water mix onto location.

Describe Area Affected and Cleanup Action Taken.*

The affected area was 48x85 with all fluids contained on location. Legendary Trucking recovered all 20bbls of oil and produced water mix and the contaminated dirt will be removed from location and replaced with fresh dirt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher

Printed Name: Sheila Fisher

Title: Field Admin Support

E-mail Address: Sheila.Fisher@dvn.com

Date: Phone: 575.748.1829

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date: 5/11/15

Expiration Date: N/A

Conditions of Approval:
Remediation per O.C.D. Rules & Guidelines Attached ☐

MIT REMEDIATION PROPOSAL NO

LATER THAN: 01/21/15

2RP-2998

* Attach Additional Sheets If Necessary