

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1514635341

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: BEU-DI-5 #004H (Heater-treater)	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-40397	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	27	20S	31E	1980	North	1848	East	Eddy

Latitude N 32.546095° Longitude W 103.854466°

NATURE OF RELEASE

Type of Release: Crude oil & produced water	Volume of Release: 12 bbls. oil and 6 bbls PW	Volume Recovered: 9 bbls oil and 3 bbls. PW
Source of Release: Heater-treater	Date and Hour of Occurrence: 5/20/15 time unknown	Date and Hour of Discovery: 5/20/15 at approximately 8:30 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT
MAY 22 2015

Describe Cause of Problem and Remedial Action Taken.*
A gasket failed on the heater-treater. The vessel was bypassed. The gasket will be replaced.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*
The spill impacted approximately 4,200 sq.ft. of caliche pad area inside the earthen containment around the process equipment. The free standing fluid was recovered with a vacuum truck. A hydro-vac will be used to remove the saturated soil around the equipment. Date to start will be based on crew availability. The spill area will be cleaned in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>Haber</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>5/26/15</i>	Expiration Date: <i>NA</i>
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: <i>5/22/15</i> Phone: 432-556-8730	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *5/28/15*

2RP-3013