		,	NM	OCD					
	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WI			Artesia ELLS		FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM131578			
h	Do not use thi abandoned wel	drill or to re-en D) for such prop	enter an roposals.		6. If Indian, Allottee or Tribe Name				
•	SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
	I. Type of Well □ Gas Well □ Other				8. Well Name and No. HALIFAX FEDERAL 2				
	2. Name of Operator Contact: JERRY W SHE MACK ENERGY CORPORATION E-Mail: jerrys@mec.com				9. API Well No. 30-005-64248-00-X1				
	3a, Address P.O. BOX 960 ARTESIA, NM 88211-0960	3b. Phone No. (include area code) Ph: 575-748-1288 Fx: 575-746-9539			10. Field and Pool, or Exploratory ROUND TANK-SAN ANDRES				
	4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description	1)			11. County or Par	ish, and S	tate	
	Sec 23 T15S R28E NWNE 33	0FNL 1400FEL				CHAVES CO	DUNTY,	NM	
	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
	TYPE OF SUBMISSION	TYPE OF SUBMISSION     TYPE OF ACTION						,	
	🛛 Notice of Intent	🗋 Acidize	🗖 Deepen	Deepen		Production (Start/Resume)		Water Shut-Off	
	_	Alter Casing	□ Fracture	□ Fracture Treat		□ Reclamation		Well Integrity	
	Subsequent Report	Casing Repair		New Construction		omplete 🛛 Other Change to Original		Other nange to Original A	
	Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back			Temporarily Abandon PD Water Disposal			
· . ·	testing has been completed. Final Ab determined that the site is ready for fi Mack Energy proposes to drill to spud of hole and setting/cer 130-150', based on COA. 8 5/4 Class C + 1% PF1, yield 1.33; cellar will be fenced. Mack Ener This will eliminate the conduct	nal inspection.) and set surface casing u menting of casing. A 20" 8" 32# J-55 ST&C New c weight 14.8ppg, 100% e ergy will move in a drilling	ising an Auger Ri hole will be drille asing will be set excess. Casing w	g. BLM will b to compete and cemente Il be capped	be notified prient bedrock at ed w/300sx 6.	or t 32gl/sx		ONSERVATIO	
·	Conductor pipe will be set if w	ellbore issues are encour	ntered.		/////S		JUN	8 2015	
-				NMOCD		•	RECL	EIVED	
		Electronic Submission # For MACK ENE mmitted to AFMSS for pro	ERGY CORPORAT	ION, sent to GLASS on 0	the Roswell 6/03/2015 (15	DRG0090SE)			
	Name (Printed/Typed) JERRY W	SHERRELL	Ti	le PRODU	JCTION CLE	RK			
	Signature (Electronic Submission)			Date 06/02/2015					
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
			т			ER		Date 06/03/2015	
-	Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu	e subject lease	Office Roswell						
	Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a tatements or representations as	crime for any person to any matter within	knowingly and its jurisdiction.	l willfully to ma	ke to any departmen	t or agend	cy of the United	
	** BLM REVI	SED ** BLM REVISE		- · · ·		Hen før F Appro			

# PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME: Mack Energy Corporation - Sherrell, Jerry LEASE NO.: NMNM131578 WELL NAME & NO.: HALIFAX FEDERAL - 2 SURFACE HOLE FOOTAGE: [330] ' F [N] L [1400] ' F [E] L BOTTOM HOLE FOOTAGE: [355] ' F [N] L [1675] ' F [E] L LOCATION: Section 023, T015. S., R 028 E., NMPM COUNTY: Chaves County, New Mexico

# 1. DRILLING:

#### DRILLING OPERATIONS REQUIREMENTS:

- A. The BLM is to be notified a minimum of 24 hours in advance for a representative to witness:
  - Spudding well,
  - Setting and/or Cementing of all casing strings,
  - BOPE tests.

The Roswell Field Office Engineer on-call phone number is: (575) 627-0205.

- B. A Hydrogen Sulfide (H2S) Drilling Operation Contingency Plan shall be activated prior to drilling into the Queen formation. A copy of the plan shall be posted at the drilling site.
- C. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- D. Include the API Number assigned to well by NMOCD on the subsequent report of setting the first casing string.
- E. The operator will accurately measure the drilling rate in feet/min to set the base of the usable water protection casing string(s) opposite competent rock. The record of the drilling rate along with the caliper-gamma ray-neutron well log run to surface will be submitted to this office as well as all other logs run on the borehole 30 days from completion.

F. Air, air-mist or fresh water and nontoxic drilling mud shall be used to drill to the base of the usable water protection casing string(s). Any polymers used will be water based and non-toxic.

## CASING:

- A. Deepest depth of usable water occurs at an approximate depth of 83 feet. The operator will run 40 feet of conductor pipe and ready mix cement to the surface. The 8-5/8 inch usable water protection casing string(s) shall be set in competent bedrock at the top of the salt between 130 feet and 150 feet.
  - If cement does not circulate to the surface, the Roswell Field Office shall be notified and a temperature survey utilizing an electronic type temperature survey with a surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
  - Wait on cement (WOC) time for a primary cement job will be a minimum 18 hours or 500 pounds compression strength, whichever is greater. (This is to include the lead cement).
  - Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compression strength, whichever is greater.
  - If cement falls back, remedial action will be done prior to drilling out that string.
- B. The minimum required fill of cement behind the 5-1/2 inch production casing is sufficient to circulate to the surface. If cement does not circulate, a temperature survey utilizing an electronic type temperature survey with a surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
- C. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.
- D. All casing shall be new or reconditioned and tested casing and meet API standards for new casing. The use of reconditioned and tested casing shall be subject to approval by the Authorized Officer. Approval will be contingent upon the wall thickness of any casing being verified to be at least 87-1/2 per cent of the nominal wall thickness of new casing.

#### PRESSURE CONTROL:

A. Prior to drilling below the 8-5/8 inch surface casing shoe, the blowout preventer assembly (BOP/BOPE) shall be installed. The BOP/BOPE shall consist of a

minimum of One Annular Preventer or Two Ram-Type Preventers and a Kelly Cock/Stabbing Valve.

- B. Before drilling below the 8-5/8 inch surface casing shoe, minimum working pressure of the blowout preventer and related equipment (BOPE) shall be 2000 psi. If operator chooses to use a control device greater than the minimum stand they will have to follow all guidelines as stated within Bureau of Land Management 43 CFR part 3160 and Onshore Oil and Gas Order No. 2 Drilling Operations.
- C. The BOPE shall be installed before drilling below the 8-5/8 inch surface casing shoe and shall be tested as described in Onshore Oil and Gas Order No. 2. Any equipment failing to test satisfactorily shall be repaired or replaced.
  - The BLM Roswell Field Office shall be notified a minimum of 24 hours in advance for a representative to witness the tests.
  - The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.
  - All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test will be submitted to the BLM Roswell Field Office at 2909 West Second Street, Roswell, New Mexico 88201.
  - Testing fluid must be water or an appropriate clear liquid suitable for sub-freezing temperatures. Use of drilling mud for testing is not permitted since it can mask small leaks.
  - Testing must be done in a safe workman like manner. Hard line connections shall be required.
  - The requested variance to test the BOPE prior to drilling below the 8-5/8 inch surface casing to the reduced pressure of 2000 psi by a third party is approved.

### 2. CLOSED LOOP SYSTEMS:

No reserve pit will be used. Steel tanks are required for drilling operations. The operator shall properly dispose of drilling contents at an authorized disposal facility. No open top tanks are permitted.