

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1517742106

Name of Company Burnett Oil Co. Inc. 3080		Contact Leslie Garvis	
Address 801 Cherry Street- Suite 1500, Ft. Worth, Texas 76102		Telephone No. 817-583-8730	
Facility Name Gissler A 2		Facility Type Tank Battery	
Surface Owner BLM		Mineral Owner BLM	
		API No. 30-015-33498 (Gissler A 24)	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	14	17S	30E	1650	South	1776	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil/Water	Volume of Release 80 bbls/210 bbls	Volume Recovered 5 bbls/25 bbls
Source of Release Fire at Tank Battery	Date and Hour of Occurrence 6/13/15 1:50	Date and Hour of Discovery 6/13/15 1850 MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM & H. Patterson, OCD - Phone Call/Follow up email 6/13/15	
By Whom? Johnny Tiltsworth/Leslie Garvis	Date and Hour 6/13/15 - Amos: 1943 MST/ Patterson 1945 MST/Email 2116 CST 4:16p	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

NM OIL CONSERVATION
ARTESIA DISTRICT

Describe Cause of Problem and Remedial Action Taken.*
Fire at battery - cause under investigation. Wells to this battery were shut in.

JUN 23 2015

RECEIVED

Describe Area Affected and Cleanup Action Taken.*
Majority of Hydrocarbons were burned during the fire. Some PW and Hydrocarbons released into the pasture after poly flowlines burned. 110'x60' pasture, 40'x30' pasture, 3'x200' pasture. 50'x60' inside firewall. Samples taken to lab. Met with J. Amos on 6/16/15 to discuss plan of remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie Garvis</i>		OIL CONSERVATION DIVISION	
Printed Name: Leslie Garvis		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Regulatory Coordinator		Approval Date: 6/26/15 Expiration Date: N/A	
E-mail Address: lgarvis@burnettoil.com		Conditions of Approval:	
Date: 6/23/15 Phone: 817-583-8730		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 7/30/15

2RP. 3009