

**NM OIL CONSERVATION**

ARTESIA DISTRICT

JUL 14 2015

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
Submit to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nAB15198485A1

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd. <u>10644</u>	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Two Marks 36 State #4 SWD Battery	Facility Type	Battery

Surface Owner	State	Mineral Owner	API No. 30-15-34833
---------------	-------	---------------	---------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	36	21S	24E					Eddy County, NM

Latitude N 32.42960° Longitude W 104.45840°

**NATURE OF RELEASE**


Type of Release	Produced water	Volume of Release	50 bbls	Volume Recovered	0 bbls
Source of Release	Power failure caused the H pump to stay off and tanks to spill over	Date and Hour of Occurrence	06/24/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	06/25/2015 @ 11:17 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES; Volume Impacting the Watercourse:			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Power failure caused the H pump to stay off causing the tank to spill 50 bbls of produced water onto the ground. The power was restored and no fluids were recovered.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is approximately 105' x 55' on location inside the lined battery. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 

Printed Name: Chancey Summers

Title: HES Lead

E-mail Address: Chancey.Summers@oxy.com

Date: 7-13-15 Phone: (432) 685-5824

**OIL CONSERVATION DIVISION**

Signed By Mike Bratcher  
Approved by Environmental Specialist:

Approval Date: 7/17/15 Expiration Date: N/A

Conditions of Approval:

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 8/20/15

\* Attach Additional Sheets If Necessary

2RP-3125