

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 8/20/15  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1524750307

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
<b>Name of Company</b> Devon Energy Production		<b>Contact</b> Garry Michael	
<b>Address</b> 6488 Seven Rivers Hwy Artesia, NM 88220		<b>Telephone No.</b> 575-513-4895	
<b>Facility Name</b> Cotton Draw Unit 153H		<b>Facility Type</b> Oil	
<b>Surface Owner</b> Federal		<b>Mineral Owner</b> Federal	
		<b>API No.</b> 30-015-38535	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	3	25 S	31 E	200	North	1980	East	Eddy

Latitude: N 32°16'62.16"

Longitude: W 103°76'35.73"

NATURE OF RELEASE

<b>Type of Release Spill</b> Oil	<b>Volume of Release</b> 40 bbls	<b>Volume Recovered</b> 35 bbls
<b>Source of Release</b> Suction Lines in the circulating pump where not closed	<b>Date and Hour of Occurrence</b> 7.19.2015 @ 4:00 AM	<b>Date and Hour of Discovery</b> 7.19.2015 @ 4:00 AM
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Jim Amos BLM Mike Bratcher OCD	
<b>By Whom?</b> Eduardo Enriquez	<b>Date and Hour</b> 7.19.2015 @ 4:56 AM 7.19.2015 @ 4:58 AM	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse</b>	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

On July 19, 2015 Pace Energy Lease Operator was driving by the Cotton Draw Unit 153 H at 4:00 AM when he noticed fluid on location. The fluid was coming from the suction lines in-the circulating pump, Lease Operator proceeded to close the valves to stop the spill.

Describe Area Affected and Cleanup Action Taken.\*

Horizon trucking was called to recover 35 bbls. Further documentation to follow.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b> Corina Moya		<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Corina Moya		<b>Approved by Environmental Specialist:</b> 	
<b>Title:</b> Field Admin Support		<b>Approval Date:</b> 8/14/15	<b>Expiration Date:</b> N/A
<b>E-mail Address:</b> corina.moya@dvn.com		<b>Conditions of Approval:</b>	
<b>Date:</b> 7.20.2015 <b>Phone:</b> 575.746.5559		<b>Attached</b> <input type="checkbox"/>	
<b>Remediation per O.C.D. Rules &amp; Guidelines</b>			

\* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 10/4/15

2RP-3241