

TRINITY RESOURCES, LLC

200 WEST FIRST STREET
SUITE 859
ROSWELL, NEW MEXICO 88203-4697

PHONE 505-622-7246
FAX 505-622-1711
EMAIL: jplandman@dfn.com

January 20, 2006

Mr. Chris Beadle
NMOCD
1301 W. Grand
Artesia, NM 88210

RECEIVED
JAN 24 2006
OOD-ARTESIA

RE: Leonard "A" State #1/API# 30-015-03603
T-19-S, R-29-E, NMPM,
Section 12: UL "B"
Eddy County, NM

Dear Mr. Beadle:

Per conversations with area field operators and engineers, we believe that the small amount of fluid that escaped, as a result of the bullet hole found in the dryhole marker on the captioned well, was the extent of what was trapped between the surface and intermediate plugs.


This well was plugged in accordance to the rules, regulations and guidelines set out by the NMOCD, witnessed and approved by your office.

Before we are forced to spend thousands of dollars to replug subject well, we request your consideration of an alternative method and/or approach, or a meeting to discuss other possibilities available to us.

Please advise.

We appreciate your help and consideration.

Sincerely,
TRINITY REOURCES LLC



Jim Pierce

Xc: Bulldog Well Service
Attention: Mr. Ralph Romero

Accepted for record - NMOCD

JAN 26 2006