

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JAN 06 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Apache Corporation <i>813</i>	Contact Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name Hummingbird Fed Com Battery	Facility Type: Battery

Surface Owner Federal	Mineral Owner	API No. 30-015-42632
-----------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	1	17S	31E	1750'	FSL	330'	FEL	Eddy

Latitude Longitude

NATURE OF RELEASE

Type of Release: Oil and produced water	Volume of Release 750 barrels of oil	Volume Recovered 750 Barrels were burned in the fire.
Source of Release: Heater Treater	Date and Hour of Occurrence 12/22/2015	Date and Hour of Discovery 12/22/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker (BLM) and Jamie Keys (NMOCD)	
By Whom? Jorge Rivera	Date and Hour 12/22/2015 ?	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A gasket failure on heater treater resulted in a hydrocarbon fire at the battery. The Loco Hills and Riverside Volunteer Fire Departments were dispatched to extinguished fire. Roustabout crews and vacuum trucks were onsite recovering standing fluid from inside the berm and storage tanks.

Describe Area Affected and Cleanup Action Taken.*

The majority of the release was contained to the lease pad except for a small area of pasture on the south side which was impacted by oil sludge carried over by fresh water from fire department.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>		OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Technician		Approval Date: <i>1/7/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: larry.baker@apachecorp.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 1/4/2016	Phone: (432) 631-6982	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *1/8/16*

2RP-3477