<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 311 S. First St., Artesia, NM 88210	State of New Mexic Energy Minerals and Natural			FOID C-141				
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505			Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.		
	-	ase Notific	cation	and Co	orrective A	ction		
				<b>OPERA</b>			al Report 🔲 Final Report	
Name of Company Devon Energy Address 6488 Seven Rivers Hwy					latt Nettles, Pro No. 575.513-57		Foreman	
Facility Name North Pure Gold 9		00210			pe Oil Well			· · · · · · · · · · · · · · · · · · ·
Surface Owner Federal Mineral Owner				Federal API No 30-015-27178				
		LOC		N OF RE	LEASE			
Unit Letter Section Township N 9 23S	Range 31E	Feet from the 330	North/	South LineFeet from the 1980East/West Line FWLCounty Eddy			· ·	
, , ,	Lat	titude: 32.3125	916	Lon	gitude: -103.784	9503		·
		NAT	TURE	OF REL				
Type of Release Produced Water (PW) & Oil				Volume of Release 3BBLS PW & 2BBLS Oil			Volume Recovered 0BBLS	
Source of Release				Date and Hour of Occurrence			Date and Hour of Discovery	
Hole in the flowline Was Immediate Notice Given?				7/24/2016 @ 9:20AM         7/24/2016 @ 9:20AM           If YES, To Whom?         7/24/2016 @ 9:20AM				
🛛 Yes 📋 No 📋 Not Required				OCD-Mike Bratcher BLM-Shelly Tucker				
By Whom?				Date and Hour				
Leonard Aguilar, Assistant Production Foreman				OCD-7/24/2016 @ 10:03AM BLM-7/24/2016 @ 10:00AM				
Was a Watercourse Reached?				If YES, Volume Impacting the Watercourse N/A				
If a Watercourse was Impacted, Des N/A	cribe Ful	ly.*		L				
<b>Describe Cause of Problem and Ren</b> 3BBLS PW and 2BBLS Oil was release shut in and the valve at the heater was	ed due to	a hole in the flow	vline loca release.	ated directly Repairs have	where the poly flo been made.	owline tr	ansitions i	nto metal pipe. The well was
<b>Describe Area Affected and Cleanu</b> 3BBLS PW and 2BBLS Oil were relea a Southwestern direction leaving pad i was 10ft by 65ft. An environmental ap	sed with (	BBLS recovered c. The approxim	ate size c	of the total ar				
I hereby certify that the information gives regulations all operators are required to public health or the environment. The should their operations have failed to a or the environment. In addition, NMC federal, state, or local laws and/or regulations and the environment of the environment.	o report an acceptanc dequately CD accep	nd/or file certain the of a C-141 rep investigate and t	release no ort by the remediate	otifications a e NMOCD m e contaminat	nd perform correct arked as "Final R ion that pose a thr re the operator of	ctive act eport" d cat to gr respons	ions for re- loes not re- round wate ibility for c	eases which may endanger ieve the operator of liability r, surface water, human health compliance with any other
Signature: Dana DeLaRosa				OIL CONSERVATION DIVISION Signed By R. Ly Brancy a				
Printed Name: Dana DeLaRosa				Approved by Environmental Specialist:				
Title: Field Admin Support				Approval Da	te: 7/26/1	p	Expiration	Date: NA
E-mail Address: dana.delarosa@dvn	com		R	Gmeidiatio	n∕peroQiC.D. F	Rules	& Guide	Attached
Date: 7/25/2016 Phone: 575	.746.5594	l	5	UBMIT RE Ater tha	MEDIATION	16	JOAL N(	1 ARP-3805