

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

**NAB1626350406** OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Lime Rock Resources II-A, L.P. <b>277558</b>	Contact Mike Barrett
Address R347-2 North 26 Street, Artesia, New Mexico 88210	Telephone No. 505-353-2644
Facility Name ASAU Trunk line release	

Surface Owner Fee	Mineral Owner State	API No. <b>30-015-</b>
-------------------	---------------------	------------------------

LOCATION OF RELEASE

Unit Letter P	Section 14	Township 18S	Range 26E	Feet from the	North/South Line FSL	Feet from the	East/West Line FEL	County EDDY
------------------	---------------	-----------------	--------------	---------------	-------------------------	---------------	-----------------------	----------------

Latitude 32.74318 Longitude 104.34817

NATURE OF RELEASE

Type of Release Hydrocarbon, produced waters, gas	Volume of Release Unknown	Volume Recovered 0 bbls
Source of Release production line	Date and Hour of Occurrence 9/3/2016 am	Date and Hour of Discovery 9/3/2016 am
Was Immediate Notice Given? Yes No <input checked="" type="checkbox"/> Not Required as release was less than 5 bbls	If YES, To Whom?	<b>NM OIL CONSERVATION ARTESIA DISTRICT</b>
By Whom?	Date and Hour	<b>SEP 15 2016</b>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	<b>RECEIVED</b>

If a Watercourse was Impacted, Describe Full

Describe Cause of Problem and Remedial Action Taken.\*

A 3" below grade FG flow line split, the line was immediately shut-in, the line was excavated and then repaired. Excavation for the repair uncovered evidence of a historic release at this location. The historic release occurred prior to acquisition of the lease by Lime Rock. The release caused by the flow line split was less than 5 bbls.

Describe Area Affected and Cleanup Action Taken.\*

The area affected by the historic release is on the edge of Fanning road (CR-44) and was measured to be 15L'x15W'. Additional evaluation is required to determine if the historic release was in such quantity as may with reasonable probability be detrimental to water or exceed the standards in Subsections A and B or C of 19.15.30.9 NMAC. Lime Rock will voluntarily provide the results of the additional investigations to OCD and, if necessary, a remediation plan consistent with Part 29.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

AMENDED

Signature:

Printed Name: Michael Barrett

Title: Production Superintendent

E-mail Address: Michael Barrett <mbarrett@limerockresources.com>

Date: 9/12/2016

Phone: 505-353-2644

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date:

9/19/16

Expiration Date:

N/A

Conditions of Approval:

Remediation per O.C.D. Rules & Guidelines ☐

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN:

10/20/16

\* Attach Additional Sheets If Necessary

2RP-3893