

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

NOV 29 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

NAB1633639499

Name of Company	WPX Energy Inc/RKI <i>246289</i>	Contact	Karolina Blaney
Address	5315 Buena Vista Dr.	Telephone No.	970 589 0743
Facility Name:	Brushy Draw Booster Station/Fed UCBHWW 1	Facility Type:	Tank Farm
Surface Owner:	Federal	Mineral Owner:	Federal
		API No.	30-015-24034

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	25	26S	29E	660	FSL	660	FWL	Eddy

Latitude: 32.005742 N Longitude: -103.944433 W

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	120 Bbls	Volume Recovered:	200 Bbls
Source of Release	Produced water tank	Date and Hour of Occurrence	11/13/2016	Date and Hour of Discovery	11/13/2016 - 1420 hrs MT
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD Heather Patterson & Michael Bratcher, BLM Shelly Tucker		
By Whom?	Karolina Blaney	Date and Hour:	11/14/16- 1302 hrs MT		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*
The cause of this spill is equipment failure; a cross arm on an electric post failed which cut off power supply to the water transfer pump. Additionally, the ESD float got stuck, didn't trigger the high water alarm notification and didn't shut in the system.

Describe Area Affected and Cleanup Action Taken.*
The spill was contained inside dirt SPCC containment berm. 200 bbls of produced water and stormwater were recovered from the secondary containment (estimated at least 80 bbls of stormwater). The impacted area was sampled for chlorides, BTEX and TPH in accordance with NM OCD Guidelines for Remediation of Leaks, Spills, and Releases. WPX will submit a workplan to OCD and BLM for the remediation of this spill.
The total ranking score for this site is 0 and the site will be remediated to levels specified in 0-9 column of the Guidelines document.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Karolina Blaney</i>	OIL CONSERVATION DIVISION	
Printed Name: Karolina Blaney	Approved by Environmental Specialist <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: <i>11/30/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: Karolina.blaney@wpxenergy.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 11/28/2016	Phone: 970-589-0743	

* Attach Additional Sheets If Necessary

2RP-4011