Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Lease Serial No. NMLC065478B

# SUNDRY NOTICES AND REPORTS ON WELLS

abandoned wei	6. If Indian, Allottee o	r Tribe Name			
SUBMIT IN T	7. If Unit or CA/Agreement, Name and/or No. NMNM70945X				
1. Type of Well	8. Well Name and No.	UT 4.44D			
☑ Oil Well ☐ Gas Well ☐ Oth	EMPIRE ABO UN	III 141B			
2. Name of Operator Contact: ISABEL HUDSON APACHE CORP E-Mail: Isabel.Hudson@apachecorp.com			9. API Well No. 30-015-22834		
3a. Address 303 VETERANS AIRPARK LANE SUITE 1000 MIDLAND, TX 79705  3b. Phone No. Ph: 432.818			rea code)	10. Field and Pool or Exploratory Area EMPIRE;ABO (22040)	
4. Location of Well (Footage, Sec., T	11. County or Parish, State				
Sec 11 T18S R27E 225FNL 2	EDDY COUNTY, NM				
12. CHECK THE A	PPROPRIATE BOX(ES) T	O INDICATE NAT	URE OF NOTICE	E, REPORT, OR OTI	HER DATA
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent	☐ Acidize	☐ Deepen	☐ Produ	ction (Start/Resume)	☐ Water Shut-Off
☑ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fra	cturing 🔲 Recla	nation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	□ New Construction	tion 🗖 Recor	nplete	Other
☐ Final Abandonment Notice	☐ Change Plans	Plug and Aba	ndon 🔀 Temp	orarily Abandon	
-	☐ Convert to Injection	☐ Plug Back	☐ Water	Disposal	
testing has been completed. Final Al determined that the site is ready for f Apache would like to perform Production Casing: 5-1/2? 15. Producing Interval: 6,060-132 Objective: Isolate open perfs a Procedure:  1. POOH with rods and tbg 2. Scan tbg and mark junk pip 3. Set CIBP @ 6,030? and du	inal inspection. the following work. Please 5# K-55 Set @ 6,225? and TA wellbore. Well being	see attachments. g evaluated for recor	npletion potential	HM ON C	CHISERVANICA  1.3 201.1  OFIVED
14. I hereby certify that the foregoing is  Name (Printed/Typed) ISABEL H	Electronic Submission #36 For APA Committed to AFMSS for pr	CHE CORP, sent to the control of the corp.  CHE CORP, sent to the corp.	ne Carlsbad	2/13/2016 ()	
Signature (Electronic S	ubmission)	Date	11/23/2016		
	THIS SPACE FO	R FEDERAL OR S	TATE OFFICE	JSE	
Approved By James	a. ams_	Title	SPET		2-7-17 Date
onditions of approval, if any, are attached ertify that the applicant holds legal or equ which would extitle the applicant to condu	itable title to those rights in the s		CFO		
itle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a createments or representations as to	rime for any person know o any matter within its jur	ingly and willfully to i	nake to any department or	agency of the United

## Additional data for EC transaction #358915 that would not fit on the form

### 32. Additional remarks, continued

- 4. Fill casing with fluid and pressure test to 500 psi 5. Record the test on a chart and submit for approval

November 23, 2016

Empire ABO Unit # M-141

Legal Name: Empire ABO Unit #141B

API # 30-015-22834 Eddy County, NM

Production Casing: 5-1/2" 15.5# K-55 Set @ 6,225'

Producing Interval: 6,060-132'

<u>Objective</u>: Isolate open perfs and TA wellbore. Well being evaluated for recompletion potential

### Procedure:

- 1. POOH with rods and tbg
- 2. Scan tbg and mark junk pipe
- 3. Set CIBP @ 6,030' and dump bail 35' of cmt
- 4. Fill casing with fluid and pressure test to 500 psi
- 5. Record the test on a chart and submit for approval

Apache Corp. Actual					
Spud: 5/21/79 Rig Release: 6/6/79		KB = GL = 3575'			
7-7/8"	8-5/8" 24# K-55 Set @ 997' CMT 700 SX CIRC SURF  5-1/2" 15.5# K-55 Set @ 62 CMT W/ 1400 SX TOC @ CMT void 4050-4722' w/no 3/94: Perf @ 960 & SQZ w/	25' Surface cement 990' to surface			
	2 3/8" TBG set @ 6130' TAC @ 5842'  DV tool @ 3968'				
		EFE CaCl wtr, 1500 gal gelled LC, 1000 gal 15%			
<b>TD</b> = 6225' <b>PBTD</b> = 6176'	3/94: Az w/ 2500 gal a5% N	Formation Tops:  Queen - Grayburg - San Andres - Glorieta - Abo -			

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if bailed) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass-the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.