f	Submit I Copy To Appropriate District Office		State of New Mexico Minerals and Natural Resources		Form C-103 Revised July 18, 2013 WELL API NO. 30-015-22658	
	<u>District 1</u> – (575) 393-6161 1625 N French Dr., Hobbs, NM 88240	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505				
	District II - (575) 748-1283 811 S. First St., Artesia, NM 88210			5. Indicate T		
	District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STAT		
	<u>District IV</u> – (505) 476-3460 1220 S St. Francis Dr., Santa Fe, NM 87505	Saina	re, (NN 87505	6. State Off 2	& Gas Lease No.	
ſ	SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Nar	ne or Unit Agreement Name	
	DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH "ROPOSALS) I. Type of Well: Oil Well 🔽 Gas Well 🛄 Other			EMPIRE ABO	EMPIRE ABO UNIT #194 [309164]	
				8. Well Num	8. Well Number K-194 (194)	
ſ	2. Name of Operator Apache Corporation				9. OGRID Number 873	
ł	3. Address of Operator			10. Pool nam	10. Pool name or Wildcat	
	3 Veterans Airpark Lane, Suite 1000 Midland, TX 79705			[22040] EMP	IRE; ABO	
4. Well Location Unit Letter J : 1500 feet from the FSL line and 2130 feet from the FEL line						
	Section 1	reet nom in Township		NMPM	County EDDY	
	AND STREET	11. Elevation (Show)	whether DR, RKB, RT, GR, 3618' GL	etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF						
	PULL OR ALTER CASING DOWNHOLE COMMINGLE			IENT JOB L]	
	CLOSED-LOOP SYSTEM				_	
	OTHER: 13. Describe proposed or com	pleted operations. (Clear	OTHER:	and give pertinent	dates, including estimated date	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
	pache completed the following work roducing Interval: 6,007'-6120'	k:				
Q	bjective: TA Wellbore. Empire Abo					
	urposes. This evaluation involves ex and a chance to lose valuable reso			e unit. Without the p	roper geological analysis, we	
P	rocedure:					
2.	. POOH with rods and pump . Scan tbg and mark junk pipe		TA status may be grar	ted after a	VIL CONSERVATION ARTESIA DISTRICT	
	. Set a CIBP @ 5,957' and dump ba Circulate fluid and pressure test ca		successful MIT test is	performed.	MAR 08 2017	
	Record the test on a chart and sub			1 1 Ja Alan tort		
э.			Contact the OCD to so	hedule the test		
5.			so it may be witnesse	d.	RECEIVED	
			so it may be witnesse	d.	RECEIVED	
	Spud Date:		so it may be witnesse	d.	RECEIVED	
ŝ	Spud Date:	Rig	so it may be witnesse Release Date:	d. 3/1/2016		
ŝ		Rig	so it may be witnesse Release Date:	d. 3/1/2016		
:]	Spud Date:	Rig	so it may be witnesse Release Date:	d. 3/1/2016		
:	Spud Date:	Rig	so it may be witnesse Release Date:	d. 3/(/2016) edge and belief.	RECEIVED	
:] :	Spud Date: I hereby certify that the information SIGNATURE Type or print name Emity Fellis	Rig	so it may be witnesse Release Date:	d. 3/(/2016) edge and belief.		
:] :	Spud Date:	Rig	so it may be witnesse Release Date:	d. 3/1/2016 edge and belief.	DATE 03/03/2017 PHONE: (432) 818-1801	

.

March 2, 2017

No. Constant State of the second State of the second second

\$

Empire ABO Unit # K-194 Legal Name: Empire ABO Unit #194 API # 30-015-22658 Eddy County, NM Producing Interval: **6,007-120**'

<u>Objective</u>: TA Wellbore. Empire Abo Unit is a former gas injection project. We are actively exploring feasibility of re-pressuring for water flood purposes. This evaluation involves extensive geology and engineering review of the entire unit. Without the proper geological analysis, we stand a chance to lose valuable resources by prematurely plugging the well at this time.

Procedure:

- 1. POOH with rods and pump
- 2. Scan tbg and mark junk pipe
- 3. Set a CIBP @ 5,957' and dump bail 35' of cmt
- 4. Circulate fluid and pressure test casing to 500 psi
- 5. Record the test on a chart and submit to OCD for approval



