Office Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 CONSEF 811 S. First St., Artesia, NW 88240 TESIA DISTI	WATION	WELL API NO. 30-015-22786
811 S. First St., Artesia, NW 882 ARTESIA DIST	QH CONSERVATION DIVISION	5. Indicate Type of Lease
District III – (505) 334-6178 ARTES 1000 Rio Brazos Rd., Aztec, NM 874-0 District IV – (505) 476-3460 RD 3 2	1220 South St. Francis Dr.	STATE FEE
District IV – (505) 476-3460 FLD V 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505	enger:	B-11593-B
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)		Empire Abo Unit (309164)
1. Type of Well: Oil Well Gas V	Vell Other	8. Well Number 376
2. Name of Operator Apache Corporation		9. OGRID Number 873
3. Address of Operator		10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 1000 M	lidland, TX 79705	Empire; Abo (22040)
4. Well Location		
Unit Letter E: 1335	feet from the North line and 70	feet from the West line
Section 35	Township 17S Range 28E	NMPM County Eddy
11.	Elevation (Show whether DR, RKB, RT, GR, etc.	<i>c.)</i>
	3685' GL	
12 Check Appro	priate Box to Indicate Nature of Notice	Report or Other Data
•••		•
NOTICE OF INTEN		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
	ANGE PLANS	RILLING OPNS.□ PAND A □ NT JOB □
DOWNHOLE COMMINGLE	THE COME GASING/CEME	N JOB
CLOSED-LOOP SYSTEM		
OTHER:	OTHER: Swab	
of starting any proposed work). S	SEE RULE 19.15.7.14 NMAC. For Multiple C	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
proposed completion or recomple		
		BTD @ 5972'. POOH w/tbg. RIH w/ 5-1/2" RBP on
2-7/8" J-55 TBG. Set RBP in perfs @ 5894'. Hydrotest all TBG. RU swab equip. Make 5 swab runs. Prep to continue to swab test perfs. 01/19/2017 Swab test. Prep to POOH w/ RBP. Add perfs @ 5910'-5944'		
01/20/2017 Latch on to RBP & release. POOH w/ 2-7/8" J-55 TBG & RBP. MIRU Renegade WL Services. RIH w/ 3-1/8" perf guns & perf ABO		
@ 5910'-14', 5928'-34', & 5940'-44'. 4 SPF @ 90 degrees phasing. POOH w/ perf guns & RDMO Renegade WL Services. Prep to RIH w/ PKF Acidize new ABO perfs.		
D1/23/2017 RIH w/ 5.5" PKR on 2-7/8" J-55 tbg. Set PKR @ 5906'. MIRU Cudd Energy Services. Titrate acid to 15.1%. Test lines to 6442#.		
		se PKR & wash salt to PBTD. Reset PKR. RU swa
equip, 18 runs. RD swab equip. Prep to RIH 01/24/2017 RIH w/pump & rods w/20' gas ar		uction to D40 Satellite. RDMOSU & rev. unit. POP.
5 1/2 1/2011 1 till till paring a 1000 til 20 gad a	ising a second start product	
Spud Date: 01/26/1979	Rig Release Date: 02/09/1979	
I hereby certify that the information above	is true and complete to the best of my knowled	lge and helief
Thereby certify that the information above	is the and complete to the best of my knowled	ige and benef.
SIGNATURE SALL Clouse	TITLE Regulatory Analyst	DATE 01/30/2017
SIGNATURE SASEL (XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	TITLE regulatory Arranyst	DATE O 1/30/2017
Type or print name Isabel Alonso	E-mail address: Isabel.alonso@a	pachecorp.com PHONE: (432) 818-1142
For State Use Only		
ADDROVED DV.	TITLE SA AA	DATE 7 - 111-17
APPROVED BY: Conditions of Approval (if any):	TITLE STAFA MANA	DATE 3-14-17