

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUN 15 2017

Submit to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1717150080

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Wesley Ryan, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-390-5436
Facility Name	Ore Ida 14 Fed B Battery	Facility Type	

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-29277
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Ore Ida 14 Fed B

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	14	24S	29E	760	South	1830	East	Eddy

Latitude: 32.2124023 Longitude: -103.9525909

NATURE OF RELEASE

Type of Release	Fire	Volume of Release	109 BBLS Oil	Volume Recovered	0 BBL Oil
Source of Release	Oil Tank	Date and Hour of Occurrence	6/1/2017 @ 8:30am	Date and Hour of Discovery	6/1/2017 @ 8:30am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM-Shelly Tucker OCD-Mike Bratcher		
By Whom?	Leonard Aguilar, Assistant Production Foreman	Date and Hour	BLM- 6/1/2017 @ 3:00pm OCD- 6/1/2017 @ 3:05pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Lightning struck a 500 BBL fiberglass oil tank causing it to catch on fire and structurally compromising it. The well was immediately shut in. Fire was out upon arrival of the Lease Operator.

Describe Area Affected and Cleanup Action Taken.\*

Approximately 109bbls oil was lost to the fire and no fluids were released to the ground. All additional fluids remained in the oil tank.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION		
Printed Name: Sarah Gallegos-Troublefield	Signed By: <i>[Signature]</i>		
Title: Field Admin Support	Approved by Environmental Specialist:		
E-mail Address: Sarah.Gallegos-Troublefield@dmv.com	Approval Date: 6/20/17	Expiration Date: N/A	
Date: 6/15/2017 Phone: 575.748.1864	Conditions of Approval: FINAL		Attached

\* Attach Additional Sheets If Necessary

Please refer to the New Mexico Oil  
Conservation Division Website for  
updated form(s) at:  
[http://www.emnrd.state.nm.us/  
OCD/forms.html](http://www.emnrd.state.nm.us/OCD/forms.html) Thank you

2RP-4256