Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD Artesia

5.

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

Lease Serial No.	NM053373	

6. If Indian, Allottee or Tribe Name

adangoneg wen. Use Form 316	u-3 (APD) for such proposals.				
SUBMIT IN TRIPLICATE - Other instructions on page 2		7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well					
V On wen Gas wen Guner		8. Well Name and No. HB 3 Federal #2			
2. Name of Operator Tap Rock Operating, LLC	9. API Well No. 30-0152-6999				
3a. Address 602 Park Point Drive, Suite 200 Golden C 80401	O 3b. Phone No. (include area code) (720) 772-5090	10. Field and Pool or Exploratory Area [11520] CEDAR CANYON;BONE SPRING			
4. Location of Well (Footage, Sec., T.R., M., or Survey Description)		11. Country or Parish. State			
660' FSL/ 1650' FWL - SW/4, SEC 3 - 24S -29E Eddy County NM		Eddy County, New Mexico			
12. CHECK THE APPROPR	IATE BOX(ES) TO INDICATE NATURE OF	NOTICE, REPORT OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION				
✓ Notice of Intent Acidize Alter Casing	Deepen Hydraulic Fracturing	Production (Start/Resume) Water Shut-Off Reclamation Well Integrity			
Subsequent Report Casing Report		Recomplete			
Final Abandonment Notice Convert to I	njection Plug Back	Water Disposal			
the proposal is to deepen directionally or recomplete ho	rizontally, give subsurface locations and measu	ting date of any proposed work and approximate duration thereof. If ared and true vertical depths of all pertinent markers and zones. Attach quired subsequent reports must be filed within 30 days following			

completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site

- is ready for final inspection.)1) MIRU workover rig.
- 2) Ensure well is dead.
- 3) Pull tubing and rods and inspect for hole or damage.
- 4) Replace damaged equipment and downhole pump if necessary.
- 5) Re-run tubing and rods.
- 6) Put well back on production.
- 7) RDMO workover rig
- * estimate 3 days for full operation

If cement remediation or casing repair is desired, a sundry must be submitted for approval prior to work being done.

Accepted for record - NMOCD

NM OIL CONSERVATION

ARTESIA DISTRICT

			AITI ESTA D	ISIRICI
			. JUL O :	3 2017
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Aaron Byrd	VP Operations		RECEI	YED TO
Signature (Lan)	Date	ACCEPT	ED FOR REC	ORD
THE SPACE FOR FEL	ERAL OR STATE	OFICE US	E 2017	
Approved by	Title	BIIDVALMO	F LAND MANAGEME	and m
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.		CARLS	BAD FIELD OFFICE	
Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any false, fictitious or fraudulent statements or representations as to any matter with		d willfully to ma	ke to any department o	r agency of the United States
(Instructions on page 2)				V.