

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

SEP 13 2017

Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1725731840

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Wesley Ryan-Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-390-5436
Facility Name	Coral PWU 28 #4H	Facility Type	Oil

Surface Owner State	Mineral Owner State	API No	30-015-39328
---------------------	---------------------	--------	--------------

LOCATION OF RELEASE

Unit Letter p	Section 28	Township 19S	Range 29E	Feet from the 330	North/South Line FSL	Feet from the 990	East/West Line FEL	County EDDY
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.625351

Longitude: -104.0745087

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	12 bbls	Volume Recovered	12 bbls
Source of Release	Oil storage tank	Date and Hour of Occurrence	9/1/2017 12:04 PM	Date and Hour of Discovery	9/1/2017 12:04 PM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		
If a Watercourse was Impacted, Describe Fully.*N/A					

Describe Cause of Problem and Remedial Action Taken.*

The hammer unions on the discharge line of the circulation pump became loose causing Oil to spill out of the storage tank. Upon discovery the valves were isolated and shut off and the union valves were immediately tighten and repaired.

Describe Area Affected and Cleanup Action Taken.*

12 BBLS of Oil was released from the storage tank. A vacuum truck was dispatched and 12 BBLS of Oil was recovered. The release originated from the Oil storage tank and was released into the lined SPCC containment. The approximate affected area is 10' x 50' on the well pad inside the lined containment. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Jennifer Reyna	OIL CONSERVATION DIVISION		
Printed Name: Jennifer Reyna	Signed By: <i>Mike Brannon</i> Approved by Environmental Specialist:		
Title: Field Admin Support	Approval Date: 9/14/17	Expiration Date: N/A	
E-mail Address: jennifer.reyna@dmv.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/> ARP-4386
Date: 9/13/2017	Phone: 575.746.5588		

* Attach Additional Sheets If Necessary