

NM OIL CONSERVATION
ARTESIA DISTRICT

OCT 13 2017

Form 3160-5
(September 2001)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires: January 31, 2004

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No.
2. Name of Operator ROCKCLIFF OPERATING NEW MEXICO LLC		6. If Indian, Allottee or Tribe Name
3a. Address 1301 MCKINNEY; STE 1300; HOUSTON TX 77010	3b. Phone No. (include area code) 713-351-0534	7. If Unit or CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SEC 13, T23S, R28E 2235' FNL & 990W' FEL		8. Well Name and No. SCB 13 FEDERAL #006
		9. API Well No. 30-015-33777
		10. Field and Pool, or Exploratory Area LOVING; DELAWARE, EAST
		11. County or Parish, State EDDY COUNTY, NEW MEXICO

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Well is on OCD inactive list. Rockcliff Operating NM LLC requests TA status for 12 months until a more economic climate exists for recompletion.

Proposed TA Procedure:

1. Pull rods and tubing from well
2. Set 5.5in CIBP @ 4,734ft
3. Tag CIBP circ hole with FW + Biocide & Corrosion inhib.
4. Spot 25 szs @ 4,734ft-4,634ft, WOC for 4hrs/Tag
5. Circulate FW + Biocide & Corrosion inhib
6. Psi test to 500psi for 30mins, BLM needs to witness

Accepted for record
NMOCDRF
10/26/17

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed) **JAMIE A. ROBINSON** Title **SR. REGULATORY DESK**

Signature **jrobinson@rockcliffenergy.com** Date **10/11/2017**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE
OCT 12 2017

Approved by _____ Title _____ Date _____
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office **BUREAU OF LAND MANAGEMENT
CARLSBAD/FIELD OFFICE**

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)



SCB # 13 Fed 6
API: 30-015-33777
Eddy County, New Mexico
UNIT E : Sec 13 : T23S : R28E : 2235 FNL & 990 FWL
Proposed TA - 10/2017

KB: 7ft
GL: 2,977ft


12-1/4in Hole
8-5/8in CSG at 585ft
TOC @ surf, 120sxs to pit
635 sxs

Formation Tops

Salt	570ft
blm of Salt	2,421ft
Delaware Sand	2,640ft
Cherry Canyon	3,500ft
Brushy Canyon	4,782ft
Bone Spring	6,255ft

DV Tool @ 3,505ft
TOC @ Surface, circ 65sxs to pit

7-7/8in Hole
5-1/2in CSG at 6,424ft
TOC @ ?
1,675 sxs



Depth	Size	Weight	CASING PROGRAM		
			Grade	I.D.	Collapse
585ft	8-5/8"	24#	J-55		
6,424ft	5-1/2"	15.5# & 17#	J-55		

Depth	Size	Weight	Grade	Threads
Unsure	2-7/8in	6.5#	J-55	EUE

Proposed TA:

1. Pull rods and tubing from well
2. Set 5.5in CIBP @ 4,734ft
3. Tag CIBP circ hole with FW + Biocide & Corrosion Inhib.
4. Spot 25 sxs @ 4,734ft-4,634ft, WOC for 4hrs/Tag
5. Circulate FW + Biocide & Corrosion Inhib
6. Psi test to 500psi for 30mins, BLM needs to witness

Pardue Perforations:
4,784' - 4,794' (60 holes) Frac in late '05

Brushy Canyon "AA" Perforations:
5902ft - 5910ft (9 shots) Acidize in '05

Brushy Canyon "A" Perforations:
5994ft - 6000ft (7 holes) Acidize in '05

Brushy Canyon "B" Perforations:
6066ft - 6072ft (7 holes) Acidize in '05

Brushy Canyon "C" Perforations:
6193ft - 6203ft (60 holes) Acidize in '05

PBTD = 6,160'

Note: This schematic is not to scale. For display purposes only.

BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972

Approved for a period of 12 months ending 10/12/2018 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands
Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
3. **Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...**

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

1. **Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.**
2. Describes the temporary abandonment procedure.
3. Attaches a clear copy or the original of the pressure test chart.
4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.
2. A procedure to plug and abandon the well.

SCB 13 Federal 6

1. Well is approved to be TA/SI for a period of 12 months or until 10/12/2018
2. This will be the last TA approval for this well.
3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 10/12/2018
4. COA's met at this time.