NIM OIL CONSERVATION ARTESIA DISTRICT

State of New Mexico **Energy Minerals and Natural Resources**

Form C-141

OCT 24 2017

Revised April 3, 2017 Submit 1 Copy to appropriate District Office in RECEIVED NMAC.

District II 811 S. First St., Artesia, NM 88210 District III Oil Conservation Division 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

District I

1625 N. French Dr., Hobbs, NM 88240

1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action													
NAB172985/1417 OGRID-#372098							ГOR						
Name of Co	mpany M	C	Contact Raquel Chacon										
							Telephone No. 281-910-0441 (cell) 575-297-0988 (office)						
Facility Name: Red Light 27-34 State Com 2H						Facility Type Oil and gas production facilities							
Surface: Owner: state Mineral: Owner:						: state API No. :3001543917							
LOCATION OF RELEASE													
Unit Letter D	Section 27	Township 23S	Range 26E	Feet from the Nort 150 Nort		South Line	Feet from the 990	East/\ West	West Line	County Eddy			
32. 28208 Latitude See list Longitude See list NAD83 NATURE OF RELEASE 104-286442													
Type of Release Fire										Volume Recovered NA			
Source of Release: braided steel line pin hole							Date and Hour of Occurrence 10/16/2017 2:30 am			Date and Hour of Discovery 10/16/2017 2:30 am			
Was Immediate Notice Given? ☐ Yes ☒ No ☐ Not Required						If YES, To Whom?							
By Whom? Jenifer Van Curen						Date and Hour 10/18/2017 9:27 am (email)							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, V	olume Impacting	the Wat	ercourse.				
If a Watercourse was Impacted, Describe Fully.* Not applicable.													
Describe Cause of Problem and Remedial Action Taken.* The discharge line of the compressor on the Red Light location began to pressure up. As a result, the PRV released gas pressure. The steel braided discharge line to the PRV had a small leak which was ignited when the compressor backfired. The well was immediately shut in and extinguished with a fire extinguisher. The braided steel line has been replaced with a steel hard line.													
Describe Area Affected and Cleanup Action Taken.* No clean up required, repairs have been made to compressor.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Raquel Chacon Signature:						OIL CONSERVATION DIVISION							
Printed Name: Raquel Chacon						Approved by Environisental Specialist /4 Disamiles							
Title: Sr. HES Environmental Professional						Approval Date: 10 24 17 Expiration Date: NIA							
E-mail Address: rchacon@marathonoil.com						Conditions of Approval:					A., 1 1 🗖		
Date: October 24, 2017 Phone: 281-910-0441(cell) 575-297-0988 (office)						FINAL				Attached ARP-4458			

Phone: 281-910-0441(cell) 575-297-0988 (office)

^{*} Attach Additional Sheets If Necessary