

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NMOCD

SUNDRY NOTICES AND REPORTS ON WELLS Artesia
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 20185. Lease Serial No.
NMNM89819

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
PATTON MDP1 18 FEDERAL 3H9. API Well No.
30-015-4433310. Field and Pool or Exploratory Area
COTTON DRAW BONE SPRING11. County or Parish, State
EDDY COUNTY, NM**SUBMIT IN TRIPLICATE - Other instructions on page 2**1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator
OXY USA INC.
Contact: JANA MENDIOLA
E-Mail: janalyn_mendiola@oxy.com3a. Address
P.O. BOX 50250
MIDLAND, TX 79710
3b. Phone No. (include area code)
Ph: 432-685-59364. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Sec 18 T24S R31E Mer NMP NENW 170FNL 1928FWL
32.224124 N Lat, 103.819432 W Lon**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Deepen
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Hydraulic Fracturing
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Plug and Abandon
	<input type="checkbox"/> Plug Back
	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Recomplete
	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Water Disposal
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Well Integrity
	<input checked="" type="checkbox"/> Other Drilling Operations

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Spud 17-1/2" hole 9/7/17, drill to 643' 9/8/17. RIH & set 13-3/8" 54.5# J-55 BTC csg @ 643', pump 20BFW spacer then cmt w/ 830sx (200bbl) PPC w/ additives 14.8ppg 1.35 yield, full returns throughout job, circ 502sx (118bbl) cmt to surface/WOC. 9/9/17 RD & Install wellhead cap.

Accepted for record - NMOCD

NM OIL CONSERVATION
ARTESIA DISTRICT

NOV 29 2017

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #389672 verified by the BLM Well Information System
For OXY USA INC., sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 09/26/2017 ()

Name (Printed/Typed) DAVID STEWART

Title SR. REGULATOR/ADVISOR

Signature (Electronic Submission)

Date 09/25/2017

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ****