

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NMOCD
Artesia

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

5. Lease Serial No. NMNM100558
6. If Indian, Allottee or Tribe Name
7. If Unit or CA/Agreement, Name and/or No.
8. Well Name and No. TUCKER DRAW 9-4 FED COM 4H
9. API Well No. 30-015-44487
10. Field and Pool or Exploratory Area PURPLE SAGE;WOLFCAMP(GAS)
11. County or Parish, State EDDY COUNTY, NM

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other
2. Name of Operator RKI EXPLORATION & PROD LLC Contact: CRYSTAL FULTON E-Mail: crystal.fulton@wpenergy.com
3a. Address 3500 ONE WILLIAMS CENTER MD35 TULSA, OK 74172
3b. Phone No. (include area code) Ph: 539-573-0218
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 16 T26S R30E 260FNL 405FEL

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

ATTN: CHRIS WALLS & JENNIFER SANCHEZ

RKI EXPLORATION & PRODUCTION, LLC REQUESTS TO PERFORM A REMEDIAL SQUEEZE FOR THE ABOVE MENTIONED WELL.

Attached is our planned procedure, a new wellbore diagram, and a CBL/CCL which has been approved by Chris Walls.

PC 3-13-18
Accepted for record - NMOCD

NM OIL CONSERVATION
ARTESIA DISTRICT

MAR 12 2018

RECEIVED

14. I hereby certify that the foregoing is true and correct. Electronic Submission #405966 verified by the BLM Well Information System For RKI EXPLORATION & PROD LLC, sent to the Carlsbad Committed to AFMSS for processing by JENNIFER SANCHEZ on 02/28/2018 ()	
Name (Printed/Typed) CRYSTAL FULTON	Title PERMITTING TECH II
Signature (Electronic Submission)	Date 02/27/2018

APPROVED

THIS SPACE FOR FEDERAL OR STATE OFFICE USE MAR 2 2018

Approved By _____	Title _____	Date _____
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		
Office _____		

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ****

9-5/8" x 7" Remedial Squeeze

Objective: The objective is to remediate the TOC behind the 7" casing to at least 200-ft above the 9-5/8" casing shoe.

API #: 30-015-44487

Procedure

1. Notify BLM at least 4 hours prior to upcoming cement job.
2. MIRU Par Five Equipment
3. Record pressure on 7" casing and 9-5/8" x 7" annulus. Bleed off pressure on 9-5/8" x 7" annulus if any.
4. Tie into 2-1/16" 5K inlet valve on wellhead to pump down 9-5/8" x 7" annulus.
5. Test cement lines to 3,000 psi.
6. Establish injection rates at 2, 3, and 4 bpm with 50 bbls of freshwater. Record pressures at each rate.
 - a. Do not exceed 2,000 psi while pumping cement job. Set pump kick out at 2,000 psi.
 - b. Discuss with drilling superintendent/engineer if additional pressure is needed.
7. Pump **534 sx, 182 bbls** of **35/65 Poz C with additives**, mixed @ 12.9 ppg & 1.91 ft³/sk
8. Displace cement with 3 bbls of freshwater
 - a. Treat freshwater with corrosion inhibitor to protect casing
9. Open other 2-1/16" 5K inlet valve to 9-5/8" x 7" annulus and monitor to see if well is on vacuum.
 - a. Close both valves and shut well in if well is on a vacuum while monitoring
10. Record pump rates and pressures. Send data to engineer to be entered into Openwells.




Tucker Draw 9-4-4H

Wellbore Diagram

Wolfcamp A (Upper)
Eddy County, NM
API #: 30-015-44487

Rig Release Date: 02/13/2018



Prepared by: Taylor Carlson
Date Prepared: 2/19/2018
email: taylor.carlson@wpxenergy.com

Revised by: Taylor Carlson
Date Revised: 2/19/2018
email: taylor.carlson@wpxenergy.com