Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMLC028992J

## SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

NMOCD Artesia

6 If Indian Allottee or Tribe Name

abandoned we	II. Use form 3160-3 (API	D) for such pro	posals. $oldsymbol{A}$	rtesia	o. It maian, And	once or Tribe	Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. BRIGHAM B 1			
2. Name of Operator ROVER OPERATING, LLC	CONNIE SWAN vanderlandok.com			9. API Well No. 30-015-04254				
3a. Address 17304 PRESTON ROAD, SUI DALLAS, TX 75252	3b. Phone No. (include area code) Ph: 918-621-6533			10. Field and Pool or Exploratory Area GRAYBURG JACKSON;SR-Q-G-S				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State			
Sec 22 T17S R30E Mer NMP SESW					EDDY COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICAT	E NATURE OF	F NOTICE,	REPORT, OR	OTHER D	ATA	
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent     ■	☐ Acidize	☐ Deepe	□ Deepen		☐ Production (Start/Resume)		☐ Water Shut-Off	
☐ Alter Casing		☐ Hydraulic Fracturing ☐ Reclam			,		Vell Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction		☐ Recomplete		. 🗆 0	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug a	☐ Plug and Abandon		▼ Temporarily Abandon			
	Convert to Injection	Plug I	☐ Plug Back		☐ Water Disposal			
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f Starting date: Upon approval MIRU POH rods, tubing TIH and set pkr 75? above to POH, RU WL, run CBL TIH with CIBP, set 75? above Contact NM OCD and conducts well, RDMO  Bond coverage: BLM Bond Fi	o perforation, test casing to perforation test casing to perforation, test casing to perforation test casing to perforation.	sults in a multiple ed only after all re to 500 psi for 3	ompletion or recording the confidence of the con	mpletion in a ring reclamation	CHED FO	m 3160-4 mus leted and the o epted fo NMOC OR APPRO	or record  OF PAL  NAL  BYATION  RICT	
14. I hereby certify that the foregoing is  Name (Printed/Typed) CONNIE	Electronic Submission # For ROVER Committed to AFMSS for	OPERATING, LI processing by	.Ć, sent to the C JENNIFER SANC	Carlsbad CHEZ on 02/2	1	RECEIVE	D//	
Signature (Electronic	Submission)		Date 02/20/20	018	APPRI	(VED/		
	THIS SPACE FO	OR FEDERAL	OR STATE	OFFICE V	SE MAR	2018		
Approved By  Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to conditions.	uitable title to those rights in the		Title Office	BUJ	CARLSBAD F	MAYAGEN HFTICE	att	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any pers to any matter with	on knowingly and in its jurisdiction.	willfully to ma	ake to any deparm	ent or agency	of the United	
(Instructions on page 2)	TOR-SUBMITTED ** O	PERATOR-S	UBMITTED *	* OPERAT	OR-SUBMIT	TED **		

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Approved for a period of 1 year ending 03/06/2019 subject to conditions of approval.

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently 'plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with wellbore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

## Bringham B 1

- 1. Well is approved to be TA/SI for a period of 1 year or until 03/06/2019
- 2. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 03/06/2019
- 3. COA's met at this time.