

District I
1625 N French Dr, Hobbs, NM 88240
District II
811 S First St, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

APR 17 2018

Form C-141
Revised August 8 2011

Oil Conservation Division
1220 South St Francis Dr
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
DISTRICT II-ARTESIA O.C.D. accordance with 19 15 29 NMAC

Release Notification and Corrective Action

NAB1811339556

OPERATOR

☒ Initial Report☒ Final Report

| | |
|---|---------------------------|
| Name of Company WPX Energy Inc/RKI * # 246289 | Contact Karolina Blaney |
| Address 5315 Buena Vista Dr | Telephone No 970 589 0743 |
| Facility Name RDX 28-9H | Facility Type Well Pad |
| Surface Owner Federal | Mineral Owner Federal |
| API No 30-015-43294 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| C | 28 | 26S | 30E | 360 | FNL | 1345 | FWL | Eddy |

Latitude: 32 0195424 N Longitude -103 8900057W

NATURE OF RELEASE

| | | |
|--|---|---|
| Type of Release Produced Water | Volume of Release 30 Bbls | Volume Recovered 30 Bbls |
| Source of Release Tank Battery | Date and Hour of Occurrence 4-8-18 | Date and Hour of Discovery 4-8-18 - 10 00 hrs MT |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Crystal NMOCD Heather Patterson & Michael Bratcher, BLM Shelly Tucker | |
| By Whom? Karolina Blaney | Date and Hour 4-9-18 8 12 hrs MT | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse N/A | |

If a Watercourse was Impacted, Describe Fully * N/A

Describe Cause of Problem and Remedial Action Taken *

The cause is mechanical failure, nipple on a water transfer pump failed due to corrosion which resulted in spilling 30 bbls of produced water inside lined SPCC containment All fluids were recovered The containment liner was inspected immediately after the spill occurred Based on the inspection, there is no evidence that the spilled fluids have left the containment

Describe Area Affected and Cleanup Action Taken *

The environment was not impacted by this spill All fluids were contained inside lined SPCC containment

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

| | | |
|--|--|---------------------|
| Signature Karolina Blaney | OIL CONSERVATION DIVISION | |
| Printed Name Karolina Blaney | Approved by Environmental Specialist Crystal | |
| Title Environmental Specialist | Approval Date 4/23/18 | Expiration Date N/A |
| E-mail Address Karolina.blaney@wpxenergy.com | Conditions of Approval | |
| Date 4-17-18 Phone 970-589-0743 | Final | Attached 2RP-4711 |

* Attach Additional Sheets If Necessary