

Substitit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-03797
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2023
7. Lease Name or Unit Agreement Name Westall A State
8. Well Number 1
9. OGRID Number 229137
10. Pool name or Wildcat Loco Hills Queen Grayburg SA

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other _____

2. Name of Operator
COG Operating LLC

3. Address of Operator
550 W. Texas, Suite 1300 Midland, TX 79701

4. Well Location
Unit Letter I 1650 feet from the South line and 330 feet from the East line
Section 36 Township 17S Range 29E NMPM County Eddy

1. Elevation (Show whether DR, RKB, RT, GR, etc.)
3553' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 hours prior to starting plugging operations.
2. Set CIBP at 2552' w/35' cement cap.
3. Circ hole with mud gel.
4. Perf at 1076' squeeze plug 50' below and above base of salt. WOC and tag.
5. Perf at 572' squeeze plug 50' below and above 8 5/8" shoe, WOC and tag.
6. Set 10 sx surface plug. 60'
7. Install dry hole marker.


I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 4/20/2006

Type or print name Jerry W. Sherrell E-mail address: DKuykendall@conchoresources.com Telephone No. (432) 685-4372
For State Use Only

APPROVED BY: Phil Hankin TITLE Field Eng DATE 4/20/06
Conditions of Approval (if any):

MACK ENERGY CORPORATION
Westfall State A #1
Sec 36 T17S R29E



- 1 Notify OCD 24hrs of plugging
- 2 Set CIBP @ 2552' w/35'cmt cap circ hole w/mud
- 3 Set 100' cmt plug 1076-976' perf, squeeze, tag
- 3 Set 100' cmt plug 572'-472' Perf & squeeze & Tag
- 4 Set 10sk surface plug
- 5 Install dry hole marker