Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT BUR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

9.	Lease Serial No.
_	NMNM05039A
100	

SUNDRY N	OTICES AND	REPORTS	ON WELLS or to re-enter and	B
Do not use this	form for prop	osals to drill	or to re-enter an A	FE

tes a If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on part of the part of	OS m include area code)	8. Well Name and N POKER LAKE I 9. API Well No. 30-015-43425	5-00-X1 or Exploratory Area	
2. Name of Operator BOPCO LP  3a. Address 6401 HOLIDAY HILL RD BLDG 5 SUITE 200  Contact: KELLY KARDO E-Mail: kelly_kardos@xtoenergy.cor	m include area code)	9. API Well No. 30-015-43425 10. Field and Pool of CORRAL CAI	5-00-X1 or Exploratory Area	
2. Name of Operator BOPCO LP  Sa. Address 6401 HOLIDAY HILL RD BLDG 5 SUITE 200  Contact: KELLY KARDO E-Mail: kelly_kardos@xtoenergy.cor  3b. Phone No. (in Ph.: 432-620-4)	m include area code)	30-015-43425 10. Field and Pool of CORRAL CAI	or Exploratory Area	
6401 HOLIDAY HILL RD BLDG 5 SUITE 200 Ph: 432-620-		CORRAL CAI	or Exploratory Area NYON	
MIDLAND, IA 19101	-	11. County or Paris	10. Field and Pool or Exploratory Area CORRAL CANYON	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			sh, State	
Sec 27 T25S R30E NESE 1980FSL 980FEL		EDDY COUN	TY, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE	E NATURE OF	NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION	TYPE OF	ACTION		
☐ Acidize ☐ Deepe	en	☐ Production (Start/Resume)	☐ Water Shut-Off	
☑ Notice of Intent ☐ Alter Casing ☐ Hydra	ulic Fracturing	☐ Reclamation	■ Well Integrity	
	Construction	☐ Recomplete	☐ Other	
☐ Final Abandonment Notice ☐ Change Plans ☑ Plug a	and Abandon	□ Temporarily Abandon		
☐ Convert to Injection ☐ Plug E	Back	■ Water Disposal		
Attach the Bond under Which the Work will be performed to provide a bond to following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notices must be filed only after all redetermined that the site is ready for final inspection.  BOPCO, L.P. respectfully submits the following plug & abandon proces and abandon. Plug and abandonment is requested due to severe hole down to retrieve the fish after multiple attempts. We will utilize a 12.5-1 blend to minimize waste instead of a Neat Class C.  1. Spot 110sks of Poz H from 3823' (70' above the top of the Delaward the Base of Salt (3719'). WOC and tag.	edure in conjunctive issues and out of 13.5 ppg 35:65  e) to 100' above alt (1250') and of	ture with a drill r inability to get Poz:H  e the top of SEE ATTAC	ATION PROCEDURE ATTACHED CHED FOR	
into our surface casing (1012'). WOC and tag.	ted for record	· NMOCD		
3. Spot 250sks of Poz H from 300' to surface.	100 100 1	. L. Lan 200 L.	C ile adve of the	
*No Descrease & Bone Spring SwD well should	be approx	ed to divil within ha	WELL STANDS OF THE	
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #412758 verified  For BOPCO LP, sen  Committed to AFMSS for processing by MUST	nt to the Carlsba	d		
Name (Printed/Typed) KELLY KARDOS	Title REGUL	ATORY COORDINATOR		
Signature (Electronic Submission)	Date 04/30/2	018		
THIS SPACE FOR FEDERAL	L OR STATE	OFFICE USE		
American By MUSTAFA HAOLIE	TitlePFTROI F	UM ENGINEER	Date 05/01/2018	
Approved By MUSTAFA HAQUE  Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office Carlsbad			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any per States any false, fictitious or fraudulent statements or representations as to any matter with	rson knowingly and	willfully to make to any departmen	nt or agency of the United	

# Additional data for EC transaction #412758 that would not fit on the form

32. Additional remarks, continued

4. Cut off WH. Install dry hole marker.

#### Poker Lake Unit 474H - Current Wellbore Schematic Wolfcamp A, 3 Mile Lateral AFE# 1702460 Eddy County: XTO ID # 996794 980' FEL, 1980' FSL SHL: Sec 27, T25S, R30E 30-015-43425 GL 3290', KB 3313' (23' AGL) API# 990' FEL, 2440' FNL Elevation BHL: Sec 10, T26S, R30E Frontier 17 (23' RKB) Rig: Water Basin Area: **General Notes** Wellhead Hole Size Casing & Cement Geology 10k (Tech Data Sheet) Notify BLM prior to spud, running casing, TVD Formation cementing, and BOP testing 17-1/2" Lead (100% OH excess) 600 sx 13.6ppg class C Top of Lead @ 0' Drill out with 8.4-8.7 ppg FW mud Isolation Plug from 300' - Surface Tail (100% OH excess) 345 sx 14.8ppg class C Top of Tail @ 712' 865' Rustler 13-3/8" 68# J-55 BTC 12-1/4 > 25' into Rustler Per BLM Isolation Plug from 1400' - 62' above Casing Shoe (950') 1,322' Top of Salt Isolation Plug from Top of Fish (3820') - 100' above Base of Salt (3719') 3,719' Base of Salt Top of Fish 3820' 3,947' Delaware Fish 4,849' Cherry Canyon Bottom of Fish 4970' 6,417' Brushy Canyon 7,463' Basal Brushy Canyon 7,730' Bone Spring 8,296' Lower Avalon Shale 8,665' 1st Bone Spring Sand 9,522' 2nd Bone Spring Sand

10392' MD

9,849' 3rd Bone Spring Lime

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

# No Delaware and Bone Spring SWD well should be approved to drill within half mile of this well.

- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a

bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.



## United States Department of the Interior

### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

### **Reclamation Objectives and Procedures**

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the nátive soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
  Operations must include adequate measures for stabilization and reclamation of disturbed lands.
  Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
  process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.

- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Linda Denniston Environmental Protection Specialist 575-234-5974

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979



Haque, Mustafa <mhaque@blm.gov>

### [EXTERNAL] Poker Lake 474H Status

1 message

Stanley, Joseph <Joseph\_Stanley@xtoenergy.com>

To: "mhaque@blm.gov" <mhaque@blm.gov>

Cc: "Rabadue, Stephanie" < Stephanie\_Rabadue@xtoenergy.com>

Mon, Apr 30, 2018 at 10:41 AM

Haque,

Per our discussion, here's a brief summary of where we're at and how we got here.

On the 474H, we had drilled to ~7990' where we ended up getting stuck and could not retrieve the BHA/drill string. We spoke with Zota to get a plug-back and sidetrack sundry submitted. We were able to successfully plug the well back and sidetrack it, getting to the approximate planned TD at 10,392'. When we were pulling out of the hole to attempt logging and then run casing, we got stuck from ~4970' to ~3820' due to severe hole stability issues. We spent ~8 days unsuccessfully attempting to work the pipe and fish it out so that we could run casing to isolate the wellbore. After 8 days attempting to do this, we came to the conclusion the hole was in such terrible shape that we would not be able to retrieve the ~1150' of BHA/string and elected to submit a sundry to P&A the wellbore and re-drill with a 4-string casing design to isolate the salt and prevent the hole issues we saw on the first 2 attempts on the 474H. Attempting to drill/mill through the ~1150' of thick/heavy BHA would have been impossible given the severe hole stability issues we had already seen.

Currently, we are in the middle of our 1<sup>st</sup> plug covering from the top of the fish at ~3820' to 100' above the bottom of the salt (3719'). We have tagged TOC at 3651' (~170' isolated) and are currently pumping cement so that we will tag at 3619' per the BLM.

Please let me know if you would like any more information.

Thanks,

Joe Stanley

Drilling Engineer - Permian

XTO Energy

**XTO - Midland District Office** 

6401 Holiday Hill Road, Building 5

Midland, TX 79707

+1 (432) 571 8239 Office

+1 (432) 250 2303 Mobile