
Form 3160-5		<u> </u>				
	UNITED STATES PARTMENT OF THE IN UREAU OF LAND MANA	NTERIOR MAY 23	2018	OMB NO Expires: Ja	APPROVED O. 1004-0137 inuary 31, 2018	
		· · ·		Lease Serial No. NMLC029342A		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to restriction II-ARTESIA O.C.D abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
SUBMIT IN	TRIPLICATE - Other inst	tructions on page 2	7	. If Unit or CA/Agree	ement, Name and/or No	
1. Type of Well Gas Well Other			8	8. Well Name and No. WOOLLEY FEDERAL 6		
2. Name of Operator COG OPERATING LLC	Contact: ABIGAIL MONTGOMERY E-Mail: Abbym@bcmandassociates.com		9	9. API Well No. 30-015-31256-00-S1		
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701		3b. Phone No. (include area code) Ph: 432-580-7161	1	0. Field and Pool or I LOCO HILLS-Q		
4. Location of Well (Footage, Sec., 7	, R., M., or Survey Description)		1. County or Parish,	State	
Sec 21 T17S R30E NESW 15	·.		EDDY COUNTY	Y, NM		
12. CHECK THE AI	PROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, R	EPORT, OR OTH		
TYPE OF SUBMISSION		TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Of	
	Alter Casing	Hydraulic Fracturing	🗖 Reclamatio	on	🗖 Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplet	te	🗖 Other	
Final Abandonment Notice	Change Plans	🛛 Plug and Abandon	Temporarily Abandon			
	Convert to Injection	Plug Back	U Water Disposal			
determined that the site is ready for f 1. Set 5 1/2" CIBP @ 4510'. C WOC & Tag (DV Tool) 2. Spot 25 sx cmt @ 2250-200 3. Spot 30 sx cmt @ 1276-100 4. Spot 50 sx cmt @ 454 '-Surf	Circulate hole w/ MLF. Pre 50': (Queen) 3046 - 00'. WOC & Tag (8 5/8'' S		.) .)			
5. Cut off well head, verify cm	t to surface, weld on Belo	w Ground Dry Hole Marker.	SEE	ATTACHED	FOR	
5. Cut off well head, verify cm	t to surface, weld on Belo	·	SEE	DITIONS O	FOR F APPROVA	
5. Cut off well head, verify cm	t to surface, weld on Belo	W Ground Dry Hole Marker.	SEE	DITIONS O	FOR F APPROVA Received	
5. Cut off well head, verify cm	t to surface, weld on Belo GC Accepted for Level dry	hole marker	SEE CON	DITIONS O	F APPROVA received	
5. Cut off well head, verify cm	t to surface, weld on Belo GC Accepted for Level dry	hole marker	SEE CON	DITIONS O	F APPROVA received	
5. Cut off well head, verify cm Below ground 14. 1 hereby certify that the foregoing is	t to surface, weld on Belo G C S Accepted for true and correct. Electronic Submission # For COG O ommitted to AFMSS for pro-	19760 verified by the BLM Wel PERATING LLC, sent to the Ca	SEE CON CON Information S Information S Info	DITIONS O	F APPROVA received	
5. Cut off well head, verify cm	t to surface, weld on Belo	A19760 verified by the BLM Wel PERATING LLC, sent to the Ca bocessing by JAMES AMOS on O Title AGENT Date 05/11/20	SEE CON CON CON CON CON CON CON CON CON CON	DITIONS O 	F APPROVA received	
5. Cut off well head, verify cm	t to surface, weld on Belo	A19760 verified by the BLM Wel PERATING LLC, sent to the Ca bocessing by JAMES AMOS on 0 Title AGENT	SEE CON CON CON CON CON CON CON CON CON CON	DITIONS O 	F APPROVA Received	
5. Cut off well head, verify cm	t to surface, weld on Belo	A19760 verified by the BLM Wel PERATING LLC, sent to the Ca bocessing by JAMES AMOS on O Title AGENT Date 05/11/20	SEE CON CON CON CON CON CON CON CON CON CON	DITIONS O 	F APPROVA received	
5. Cut off well head, verify cm	t to surface, weld on Belo G C S Accepted for Level Lay true and correct. Electronic Submission # For COG O ommitted to AFMSS for pro- MONTGOMERY Submission) THIS SPACE FO A Approval of this notice does intable title to those rights in the	A19760 verified by the BLM Well PERATING LLC, sent to the Ca pocessing by JAMES AMOS on 0 Title AGENT Date 05/11/20 DR FEDERAL OR STATE O Title Support	SEE CON CON CON CON CON CON CON CON CON CON	DITIONS O 	F APPROVA RECEIVED	

COG Operating LLC


٩

.



SH

COG Operating LLC



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper, than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/Condition of Approval for Lesser Prairie-Chicken:</u> From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted