

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTRECEIVED
OCD ArtesiaFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMNM14842

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.
NMNM1053428. Well Name and No.
T BASSETT-BIRNY 19. API Well No.
30-015-22370-00-S210. Field and Pool or Exploratory Area
EMPIRE-ABO11. County or Parish, State
EDDY COUNTY, NM

SUBMIT IN TRIPLICATE - Other instructions on page 2

DISTRICT ARTESIA O.C.D.

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

MATADOR PRODUCTION COMPANY

Contact: DUSTY THORNHILL

E-Mail: dthornhill@matadorresources.com

3a. Address

ONE LINCOLN CENTER 5400 LBJ FREEWAY SUITE 1500
DALLAS, TX 75240

3b. Phone No. (include area code)

972.371.5405

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 7 T18S R29E NWSE 1980FSL 1980FEL

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

BLM BOND NO. NMB001079
SURETY BOND NO. RLB0015172GC 5-31-18
Accepted for record - NMOCDSEE ATTACHED FOR
CONDITIONS OF APPROVAL

Notify BLM minimum 24 hours before starting operations.

MIRU, Safety Meeting, ND WH, NU BOPs

1. RIH w/ tbg. Spot 30 sx CI H cmt on top of stuck RBP @ 10,054'. WOC & Tag. 200' plug min.

2. PU w/ tbg to 8,275' and spot 25 sx CI H cmt. WOC & Tag.

3. PU w/ tbg and RIH w/ perf guns. Perf @ 6,276' & squeeze 25 sx CI C cmt. WOC & Tag. 160' min.

4. PU w/ tbg and RIH w/ perf guns. Perf @ 3,805' & squeeze 25 sx CI C cmt. WOC & Tag. 140' min.

5. PU w/ tbg and RIH w/ perf guns. Perf @ 2,950' & squeeze 50 sx CI C cmt. WOC & Tag. 245' min.

6. PU w/ tbg and RIH w/ perf guns. Perf @ 1,313' & squeeze 25 sx CI C cmt. WOC & Tag. 100' min.

7. PU w/ tbg and RIH w/ perf guns. Perf @ 1,008' & squeeze 25 sx CI C cmt. WOC & Tag. 100' min.

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #407565 verified by the BLM Well Information System
For MATADOR PRODUCTION COMPANY, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 03/16/2018 (18PP1311SE)

Name (Printed/Typed) DUSTY THORNHILL

Title ASSOCIATE LANDMAN

Signature (Electronic Submission)

Date 03/13/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #407565 that would not fit on the form

32. Additional remarks, continued

8. PU w/ tbg and RIH w/ perf guns. Perf @ 476'. Circulate cmt to surface. RDMO.

9. Notify BLM minimum 4 hours prior to cutting WH. Cut off wellhead and install above ground marker as per BLM specs.

Mud laden fluid of 25 sx per 100 bbls water will be placed between plugs.


The point of contact for any operational issues regarding this well is Chris Villarreal, Operations Engineer, and can be reached at cvillarreal@matadorresources.com

MATADOR PRODUCTION COMPANY
 Travis Bassett-Birney #1
 1980' FSL & 1980' FEL Sec 7 - 18S - 29E
 Eddy County, NM
 API: 30-015-22370
PROPOSED P&A WELLBORE SCHEMATIC
 Spudded: 12/15/1977

AS OF 03/07/17

	Casing Information		Type	Weight lb/ft	Joints	Depth Set
	Hole Size	Casing Size				
Surface	17 1/2	12 3/4		53.5	11	416
Intermediate	11	8 5/8	J-55	24, 28	69	2900
Production	7 7/8	5 1/2	N-80	17	280	11,210

Capacity
 5 1/2" 17# csg



Cementing Record	
Surface	425 sks CI "C"
Intermediate	300 sks of HLW & 200 sks CI "C"
Production	875 sks of CI "H" (TOC @ 7950')

Geologic Markers	
Yates	958
Seven Rivers	1263
Bowers	1693
Queen	1926
Penrose	2080
Grayburg	2295
San Andres	2695
Glorieta	3755
1st BS	6226
2nd BS	7125
3rd BS	8010
Wolfcamp	8225
Pennsylvanian	9210
Cisco	9265
Canyon	9815
Strawn	10010
Atoka	10321
Morrow	10592
Lower Morrow	10898
Chester	11222
TD	11400

**BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972**

**Permanent Abandonment of Federal Wells
Conditions of Approval**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety (90)** days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. **Notification:** Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. **Blowout Preventers:** A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. **Mud Requirement:** Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. **Cement Requirement:** Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.**

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.