Form 3160-5 (June 2015)

Subsequent Report

Final Abandonment Notice

JUN & 0 5018

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

BUREAU OF LAND MANAGEMENTICT II-ART A PLOSIC

5. Lease Serial No. 00017280

SUNDRY NOTICES AND REPORTS ON WELLS
not use this form for proposals to drill or to re-enter an

Alter Casing

Casing Repair

Change Plans

Convert to Injection

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and withfull

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

6. If Indian, Allottee or Tribe Name

N/A abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well 8. Well Name and No. South Lucky Lake QN UT 1D Oil Well Gas Well **✓** Other 9. API Well No. 30-005-60207 2. Name of Operator Bar V Barb, LLC 10. Field and Pool or Exploratory Area 3a. Address PO BOX 4435 3b. Phone No. (include area code) Roswell, NM 88202 (575) 973-1346 Queen Formation 11. Country or Parish, State 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) L-22-15S-29E 2310 FSL 330 FWL United States, NM, Chaves County 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)

Hydraulic Fracturing

New Construction

Plug and Abandon

Plug Back

This is notification that Bar V Barb, LLC is taking over operations of this plugged well in the South Lucky Lake Queen Unit and is submitting for change of operator.

Bar V Barb, LLC., as new operator, acceptst all applicable terms, conditions, stipulations and restrictions concerning operations conducted ont his lease, or portion o flease described.

Bond Coverage: BLM Bond File No.: NMB001321

Change of Operator Effective: December 15, 2015

GC 6-21-18 Accepted for record NIMOCD

Reclamation

Recomplete

Temporarily Abandon

Water Disposal

Former Opertator: Tandem Energy Corporation (236183)

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Well Integrity

Other

			/		\	$\mathbf{\Sigma}$	=		/
14. I hereby certify that the foregoing is true and correct. Name ( <i>Printed/Typed</i> )  Steve Oldfield	Owner/Operator						3/		
Signature Sta Old get	Date				08/04	/201/6	$\searrow$	_	
THE SPACE FOR FED	ERAL	OR S	TATE	OFICE	USEKU	V/LL		A	
Approved by	Ť	tle			JUN 7 8/	1018			
Conditions of approval, if any, are attached. Approval of this notice does not warrar certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.		ffice	X	RORLAU	OF LAND M	ANAGEI	P	$\int \int$	T_

(Instructions on page 2)

## BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

## Change of Operator of Wells on Federal Lands Conditions of Approval

- 1. Tank battery must be bermed/diked (must be able to contain 1-1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Bob Hoskinson at (575) 627-0218 for inspection and to resolve environmental issues.
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with the New Mexico State BLM office in Santa Fe, NM.