Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



FORM APPROVED OMB NO. 1004-0137


	January 31, 2018
Lease Serial No.	


SUNDRY NOTICES AND REPORTS ON WELLS 1 2018

Do not use this form for proposals to drill or to respire an abandoned well. Use form 3160-3 (APD) for such proposals.

NMNM96222

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instruction 18 Triple 2				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well					8. Well Name and No. ORE IDA 14 FED D 2	
2. Name of Operator Contact: MAX LUBITZ					9. API Well No.	
DEVON ENERGY PRODUCTION COM Mail: max.lubitz@dvn.com				30-015-28930-00-S1		
3a. Address 333 WEST SHERIDAN AVENUE OKLAHOMA, OK 73102 3b. Phone No Ph: 580-30			. (include area code) 2-4593		10. Field and Pool or Exploratory Area PIERCE CROSSING	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State		
Sec 14 T24S R29E SWNW 1980FNL 330FWL			EDDY COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTI	
TYPE OF SUBMISSION			TYPE OF	ACTION		
Notice of Intent ■ Notice of Intent Notice of	☐ Acidize	☐ Dee	☐ Deepen		on (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Hyd	☐ Hydraulic Fracturing		tion	■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	□ Nev	■ New Construction		lete	Other
☐ Final Abandonment Notice	☐ Final Abandonment Notice ☐ Change Plans ☐ Plug and Abandon		☐ Tempora	☐ Temporarily Abandon		
☐ Convert to Injection		Plug	□ Plug Back		☐ Water Disposal	
1. MIRU P&A Unit. 2. Set CIBP @ 4390' 3. Spot 25 sx (250') CI C from 4. Spot 25 sx (250') CI C from 5. Spot 25 sx (250') CI C from 6. Spot 50 sx (500') CI C from 7. Perf csg @ 700'. 8. Eump 175 sc CI C in/out to 9. Cut WH off. Set dry hole ma	4140'-4390'. Tag. (Open- 6716-6466-(T. Bone Spri 5457'-5657'. Tag. (DV too 3000'-3500'. Tag. (T. Bell 3//9 - 2770 (Surface. (T. Salt 749'. sho	perfs at 4410 ng 6716') — ol at 5507') 64 Ganyon 304 7 / D < /	6, 8-5/8 shoe 306 8-5/8 shoe 306 8-5/8 shoe 306 70 273	(9) soc 72 (9) soc 72 (1) soc 72 (2) coo 0	t CIBPE 25 SX cm	(25 St min. 7/8: 4360. Spot t, sez cont (5-14).
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #	431948 vorifie	d by the Bi M Well	NDITE	ONS OF AP	PROVAL
Comm	For DEVON ENERG	Y PRODUCTIÓ	ON COM LP, sent	to the Carlsb	ad	
Committed to AFMSS for processing by DEBORAH MCKINNEY on 08/23/2018 (18DLM0594SE) Name (Printed/Typed) MAX LUBITZ Title ENGINEER						
						 · <u></u>
Signature (Electronic S	Submission)		Date 08/20/20	018		
	THIS SPACE FO	R FEDERA	L OR STATE (OFFICE US	SE 	
Approved By James a. Comos		Title Such	V. AE	ア	9-8.18 Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu	uitable title to those rights in the	not warrant or subject lease	Office Car	V. AE		
Nitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any pe	rson knowingly and ithin its jurisdiction.	willfully to ma	ke to any department or	agency of the United





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.