AUG 1 7 2018

TITLE Staff Mg DATE 8.20-18

DISTRICT II-ARTESIA O.C.D. Submit One Copy To Appropriate District State of New Mexico Form C-103 Office Revised November 3, 2011 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-015-36384 District II **OIL CONSERVATION DIVISION** 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE FEE \square 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District 1V 1220 S. St. Francis Dr., Santa Fe, NM 36900 87505 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A **RDX 16** DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 003 1. Type of Well: Oil Well Gas Well Other 9. OGRID Number 2. Name of Operator **RKI EXPLORATION & PRODUCTION, LLC** 246289 3. Address of Operator 3500 ONE WILLIAMS CENTER MD 35 10. Pool name or Wildcat TULSA, OK 74172 WILDCAT G-03 S263016K; BONE SPRING 4. Well Location : 990 feet from the S line and 990 feet from the Unit Letter Township 26S Range 30E **NMPM** 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,082' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ PERFORM REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS P AND A **PULL OR ALTER CASING** MULTIPLE COMPL CASING/CEMENT JOB \Box □ Location is ready for OCD inspection after P&A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from nonretrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule an inspection. TITLE Permit Technician II **SIGNATURE** TYPE OR PRINT NAME Caitlin O'Hair E-MAIL: caitlin.ohair@wpxenergy.com PHONE: 539-573-3527 For State Use Only

APPROVED BY: