Fonu 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM83037

UNDRY NOTICES AND REPORTS ON WELLS	
ot use this form for proposals to drill or to re-enter an	

Do n 6. If Indian, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well 8. Well Name and No. JONES CANYON 4 FED 4 ☑ Oil Well ☐ Gas Well ☐ Other Name of Operator Contact: DAVID STEWART 9. API Well No. OXY USA WTP LIMITED PTNRSHIP E-Mail: david stewart@oxy.com 30-015-30487-00-S1 3a. Address 10. Field and Pool or Exploratory Area 3b. Phone No. (include area code) NM OIL CONSERVATION Ph: 432-685 INDIAN BASIN-STRAWN HOUSTON, TX 77210 ARTESIA DISTRICT 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Sec 4 T22S R24E SWNW 2714FNL 271FWL EDDY COUNTY, NM SFP 20 2018 12. CHECK THE APPROPRIATE BOX(ES) TO INITEGENT OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Acidize Deepen □ Production (Start/Resume) ■ Water Shut-Off ■ Notice of Intent ☐ Alter Casing ☐ Hydraulic Fracturing □ Reclamation ■ Well Integrity Subsequent Report □ Casing Repair ■ New Construction ☐ Recomplete □ Other ☐ Final Abandonment Notice □ Change Plans Plug and Abandon □ Temporarily Abandon □ Convert to Injection ☐ Plug Back ■ Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 8/27/18 - MIRU PU GC 9-20-18 Accepted for record · NMOCD RECLAMATION PROCEDURE

8/28/18 - NDWH, NU BOP & Hydrill, prep to POOH w/ tbg & ESP.

8/29/18 - RU spoolers, start to POOH w/ tbg & ESP, rig broke down.

8/30/18 - Continue to POOH & LD w/ tbg & ESP. RIH w/ gauge ring, tag up @ 7810', POOH. RIH & set CIBP @ 7774', POOH.

8/31/19 - RIH w/ tbg & tag <u>CIBP @ 7774'</u>, circ well w/ 10# MLF, M&P 40sx CI H cmt, Calc TOC-7528'. PUH to 7333', M&P 40sx CL H cmt, PUH, WOC.

ATTACHED

RECLAMATION DUE 3-14-'19'

14. I hereby certify that the	ne foregoing is true and correct. Electronic Submission #435519 verifie For OXY USA WTP LIMITED P Committed to AFMSS for processing by DEBO	NRSHII	o, sent to	the Carlsbad	
Name (Printed/Typed)	DAVID STEWART	Title	SR. RE	GULATORY ADVISOR	
Signature	(Electronic Submission)	Date 09/17/2018			
	THIS SPACE FOR FEDERA	L OR	STATE	CICEPTED FOR RECO	RD
Approved By		Title			Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office		SEP 1 to 2018	
Title 18 U.S.C. Section 1001 States any false, fictitious	and Title 43 U.S.C. Section 1212, make it a crime for any peor fraudulent statements or representations as to any matter wi	rson kno ithin its j	wingly and urisdiction.	WUREAU OF LAND MANAGEMEN	gency of the United

Additional data for EC transaction #435519 that would not fit on the form

32. Additional remarks, continued

9/4/18 - RIH & tag cmt @ 7089', POOH. RIH & set pkr @ 4609'. RIH & perf @ 4957', EIR @ 2BPM @ 300#, M&P 55sx CL C cmt, SI, WOC.

9/5/18 - Rel pkr, RIH to 4852', no tag. Notify BLM, rec appr to pump another plug. Set pkr @ 4609', M&P 55sx CL C cmt, SI WOC. RIH to 4950', no tag. PUH & set pkr @ 4300', M&P 100sx CL C cmt w/ 2% CaCl2, SI WOC.

9/6/18 - RIH to 4915', no tag. Notify BLM, rec appr to pump another plug. PUH & set pkr @ 4285', M&P 100sx CL C cmt w/ 2% CaCl2, SI WOC. RIH to 4975', no tag, PUH.

9/7/18 - PUH & set pkr @ 4600', M&P 100sx CL C cmt w/ 2% CaCl2, SI WOC. RIH to 4950', no tag. PUH & set pkr @ 4600', M&P LCM w/ 3bbl FW followed by 100sx Cl C cmt w/ 2% CaCl2, SI, WOC.

9/10/18 - RIH to 4978', no tag, PUH & set pkr @ 4600'. M&P 300sx CL C cmt w/ 2% CaCl2, SI WOC. RIH to 4978', no tag, PUH & set pkr @ 4600'.

9/11/18 - Load hole w/ FW, w/ returns to surface, M&P 300sx CL C cmt w/ 2% CaCl2, SI WOC. RIH & tag cmt @ 4653', PUH, SI.

9/12/18 - PUH to 2331', circ hole w/ 10# MLF, pressure csg to 500#, tested good. Set pkr.@ 2331', RIH & perf @ 2680', attempt to EIR, no rate or loss. Notify BLM rec appr to spot plug. RIH to 2741', M&P 35sx CL C cmt, SI WOC.

9/13/18 - RIH & tag cmt @ 2611'. Notify BLM, spot add?l plug. RIH to 2611', M&P 25sx CL C cmt, Calc TOC-2465', POOH. RIH & set pkr @ 1323', RIH & perf @ 1650', EIR @ 1.5bpm @ 500# w/ returns to surface. M&P 45sx CL C cmt, PUH, WOC. RIH & tag cmt @ 1508', PUH & set pkr @ 913'. RIH & perf @ 1250', attempt to EIR, no rate or loss. Notify BLM rec appr to spot plug. RIH to 1291', M&P 30sx CL C cmt, PUH, WOC.

9/14/18 RIH & tag cmt @ 1105', PUH & set pkr @ 31'. RIH & perf @ 250', EIR @ 1bpm @ 900# w/ no returns. Notify BLM_rec appr to pump cmt. ND BOP, NUWH, M&P 100sx CI C cmt, left csg full of cmt, no returns to surface. RDPU.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612