

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

WELL API NO. 30-015-25866	
5. Indicate Type of Lease STATE ☒ FEE ☐	
6. State Oil & Gas Lease No. V-3589	
7. Lease Name or Unit Agreement Name PAULINE ALB STATE	
8. Well Number 6	
9. OGRID Number 25575	
10. Pool name or Wildcat SAND DUNES; DELAWARE, WEST	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator EOG Y RESOURCES INC	
3. Address of Operator PO BOX 2267 MIDLAND, TX 79702	
4. Well Location Unit Letter J : 1980 feet from the SOUTH line and 1980 feet from the EAST line Section 32 Township 23S Range 31E NMPM County Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3370' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

EOG proposes to P&A this wellbore ASAP using the following procedure:

- Perf @ 4180'
1- Set CIBP @ 7980', set cmt plug @ 7980-7460' w/115 sxs CL H cmt WOC, Tag TOC
2- Set cmt plug @ 4220-4100' w/25 sxs CL C cmt, WOC, Tag TOC Attempt to sqz. Csg Shoe
3- Perf 7" csg @ 3800', sqz 3800-3650' w/45 sxs CL C cmt, WOC, Tag TOC
700' → 4- Perf 7" csg @ 800', sqz 800-650' w/45 sxs CL C cmt, WOC, Tag TOC Attempt to sqz Csg Shoe
5- Perf 7" csg @ 435' sqz 435' to surface w/160 sxs cmt, verify

(1A) CIBP @ 7420' w/255Ks C/H cmt WOC + Tag NM OIL CONSERVATION

Notify OCD 24 hrs. prior to
any work done.

ARTESIA DISTRICT

SEP - 5 2018

Spud Date:

Rig Release Date:

RECEIVED

* See Attached COAs Must be Plugged by 9-10-19
I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Kay Maddox

TITLE Regulatory Analyst

DATE

9/4/2018

Type or print name Kay Maddox

E-mail address: kay_maddox@eogresources.com

PHONE: 432-686-3658

For State Use Only

APPROVED BY:

[Signature]

TITLE

Staff Mgr


DATE

9-10-18

Conditions of Approval (if any):

PAULINE ALB STATE #6

APR: 30-015-25866



Well Equipment Report

PAULINE ALB STATE #6

VERTICAL - Original Hole, 6/18/2015 9:00:00 PM

MD (ftKB)

Vertical schematic (actual)

0.0

21.3

24.0

648.0

671.9

3,799.9

4,129.9

4,153.9

5,816.9

6,183.1

7,412.4

7,416.3

7,511.2

7,528.9

7,702.1

7,706.0

7,762.1

7,777.9

7,868.1

7,936.0

7,937.3

7,938.0

7,941.9

7,974.4

7,975.1

8,037.1

8,044.9

8,879.9

9,040.0

11,454.1

11,665.0

11,928.1

12,000.0

12,023.9

12,831.0

13,225.1

13,616.1

14,009.8

14,015.1

14,295.9

14,299.9

14,430.1

14,450.1

14,520.0

14,532.2

14,713.9

14,724.1

15,034.1

Surface Casing; 13 3/8; 24.0; 648.0 ftKB; 672.0 ftKB

Cement; 24.0

Casing Description; 2 7/8; 21.3; 7,391.00; 7,412.3

Design; 3,800.0; 4/22/2009

Intermediate Casing; 9 5/8; 24.0; 4,130.0 ftKB; 4,154.0 ftKB

Cement; 24.0

Tie back 7" @; 6,183.0; 4/22/2009

Anchor / Catcher; 5 1/2; 7,412.3; 4.00; 7,416.3

Perforated; 7,511.0-7,529.0 ftKB

Perforated; 7,702.0-7,706.0 ftKB

Perforated; 7,762.0-7,778.0 ftKB

Perforated; 7,868.0-7,936.0 ftKB

Seating Nipple; 2 7/8; 7,937.2; 0.60; 7,937.8

Slotted Sub; 2 7/8; 7,937.8; 4.00; 7,941.8

Tubing; 2 7/8; 7,941.8; 32.56; 7,974.4

Bull Plug; 2 7/8; 7,974.4; 0.60; 7,975.0

Perforated; 8,037.0-8,045.0 ftKB

Perforated; 8,037.0-8,045.0 ftKB

Plug; 8,880.0 ftKB; 9,040.0 ftKB

Plug; 11,454.0 ftKB; 11,928.0 ftKB

Production Casing; 7; 24.0; 12,000.0 ftKB; 12,024.0 ftKB

Plug; 12,831.0 ftKB; 13,225.0 ftKB

Plug; 13,616.0 ftKB; 14,010.0 ftKB

CIBP - Cast Iron Bridge Plug; 4; 14,010.0-14,015.0

Perforated; 14,296.0-14,300.0 ftKB

CIBP - Cast Iron Bridge Plug w/ Cement; 5; 14,430.0-14,450.0

Perforated; 14,520.0-14,532.0 ftKB

Perforated; 14,714.0-14,724.0 ftKB

Liner; 4 1/2; 24.0; 15,034.0 ftKB; 15,034.0 ftKB

Cement; 11,665.0 ftKB; 15,034.0 ftKB

API# 3001525866

County Eddy

State New Mexico

Surface Legal Location SEC 32, TWP 23S, RNG 31E, UNIT J, Eddy CO., NM

KB-Grd (ft) 24.00

Job Category Workover

Primary Job Type Equipment Failure

Department Production

Start Date 6/18/2015

End Date 6/26/2015

Casing Strings

Casing Description	OD (in)	Top Depth (ftKB)	Set Depth (ftKB)
Surface Casing	13 3/8	0.0	648.0
Intermediate Casing	9 5/8	0.0	4,130.0
Production Casing	7	0.0	12,000.0
Casing Description	OD (in)	Top Depth (ftKB)	Set Depth (ftKB)
Liner	4 1/2	11,665.0	15,034.0

Tubing Strings

Tubing Description	Run Date	Set Depth (ftKB)	Wellbore
Tubing	7/28/2007	7,975.0	Original Hole

Tubing Components

Joints	Item Description	Length (ft)	OD (in)	Grade	Wt (lb/ft)	Top (ftKB)	Btm (ftKB)	Cum Length (ft)
227	Tubing	7,391.00	2 7/8	J-55	6.50	21.3	7,412.3	7,953.72
1	Anchor / Catcher	4.00	5 1/2			7,412.3	7,416.3	562.72
16	Tubing	520.96	2 7/8	J-55	6.50	7,416.3	7,937.2	558.72
1	Seating Nipple	0.60	2 7/8			7,937.2	7,937.8	37.76
1	Slotted Sub	4.00	2 7/8			7,937.8	7,941.8	37.16
1	Tubing	32.56	2 7/8	J-55	6.40	7,941.8	7,974.4	33.16
1	Bull Plug	0.60	2 7/8			7,974.4	7,975.0	0.60

Rod Strings

Rod Description	Run Date	Set Depth (ftKB)
Tapered Rod String	6/18/2015	7,915.0

Rod Components

Joints	Item Description	Length (ft)	OD (in)	Grade	Top (ftKB)	Btm (ftKB)	Cum Len (ft)
1	Polished Rod	30.00	1 1/2		-3.0	27.0	7,918.00
1	Pony Rod	2.00	1	HS	27.0	29.0	7,888.00
1	Pony Rod	4.00	1	HS	29.0	33.0	7,886.00
1	Pony Rod	8.00	1	HS	33.0	41.0	7,882.00
99	Sucker Rod - N97	2,475.00	1	HS	41.0	2,516.0	7,874.00
102	Sucker Rod - N97	2,550.00	7/8	HS	2,516.0	5,066.0	5,399.00
103	Sucker Rod - N97	2,575.00	3/4	HS	5,066.0	7,641.0	2,849.00
10	Sucker Rod - N97	250.00	1	HS	7,641.0	7,891.0	274.00
1	20 - 125 - RHBC - 24 - 4 Rod Pump	24.00	1 3/4		7,891.0	7,915.0	24.00

Pumping Units

API Designation	Description	Install Date	Installed Condition	Manufacturer	Crank Type	
C-640-365-168				American		
Current Stroke...	SPM	Stroke Hole	User Text 2	Sheave Size (in)	Max Pitman Rod...	Gear Box SN
124.00	6			6 1/2		

Pumping Prime Movers

Make	Model	Type	SN	Install Date	Installed Cond	Removed...
American		Electric				
RPM (rpm)	# Belts	Belt Model	Belt Length (in)	Belt X-sec	Sheave Size (in)	

CONDITIONS FOR PLUGGING AND ABANDONMENT

District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, **Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.**

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal – commercial or private – shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. If the well is not plugged within 1
7. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
8. **Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.**
9. Produced water **will not** be used during any part of the plugging operation.
10. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
11. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
12. **Class 'C' cement will be used above 7500 feet.**
13. **Class 'H' cement will be used below 7500 feet.**
14. **A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged**
15. **All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing**

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
17. **A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.**
18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, **(WOC 4 hrs and tag).**
19. **No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.**
20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) **Potash---** (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, **WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.**
21. **If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing**

DRY HOLE MARKER REQUIREMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)-----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)