Energy, Minerals and Natural Resources Revised July 18, 201
Dearhet III - (575) 748-1233 811 S First S, Anesia, NM 8210 Distinct III - (595) 334-6178 Distinct III - (595) 346-63460 Distinct IV - (595) 476-3460 Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILLO R TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PREMIT' (FORM C-101) FOR SUCH PROPOSALS. 1. Type of Well: Oil Well
Santa H. Aresia, MM 88210 Substitut Color Substitut
Santa Fe, NM 87505 Santa F
Santa Fe, INM 8/505 State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROFOSALS.) 1. Type of Well: Oil Well
SUNDRY NOTICES AND REPORTS ON WELLS The control of the control
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: Oil Well
ROPOSALS.) 1. Type of Well: Oil Well
2. Name of Operator COG Operator COG Operator COG Operator 10. Pool name or Wildcat 10. Pool nam
COG Operating, LLC 3. Address of Operator 10. Pool name or Wildcat 600 W. Illinois Ave, Midland, TX 79701 10. Pool name or Wildcat Red Lake Q-Grbg-SA
3. Address of Operator 10. Pool name or Wildcat Red Lake Q-Grbg-SA
Red Lake Q-Grbg-SA
Unit Letter P : 660 feet from the S line and 584 feet from the E line Section 22 Township 17S Range 28E NMPM County Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3585' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JOB PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated do of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 09/13/18 MIRU plugging equipment. Removed horses head. POH w/ rods & pump. Dug out cellar, 09/14/18 ND well head, NU BOP. Set 5 ½" CIBP @ 2232'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 30 sx class C cmt @ 2232-1936 WOC. 09/17/18 Tagged plug @ 1844'. Spotted 25 sx class C cmt w/ 2% CACL @ 905-658'. WOC. Tagged plug @ 640'. Perf'd c @ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt w/ 2% CACL @ 905-658'. WOC. Tagged plug @ 640'. Perf'd c @ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt @ 603' & circulated to surface. Rigged down & moved off. [09/22/1B] Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Groundry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
Section 22 Township 178 Range 28E NMPM County Eddy
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PAND A DOWNHOLE COMMINGLE COMMENCE ORILLING OPNS PAND A DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated do of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 09/13/18 MIRU plugging equipment. Removed horses head. POH w/ rods & pump. Dug out cellar, 09/14/18 ND well head, NU BOP. Set 5 ½" CIBP @ 2232'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 30 sx class C cmt @ 2232-1936 WOC. 09/17/18 Tagged plug @ 1844'. Spotted 25 sx class C cmt w/ 2% CACL @ 905-658'. WOC. Tagged plug @ 640'. Perf'd c @ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt @ 603' & circulated to surface. Rigged down & moved off. (194222/18) Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Groundry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PAD
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PAND A DIL CONSERVATION PAND A ALTERING CASING ALTERING CASING PAND A ALTERING CASING ALTERING CASING COMMENCE DRILLING OPNS. PAND A ALTERING CASING PAND A ALTERING CASING COMMENCE DRILLING OPNS. PAND A ALTERING CASING PAND A ALTERING CASING PAND A ALTERING CASING PAND A ALTERING CASING COMMENCE DRILLING OPNS. PAND A ALTERING CASING PAND A ALTERING CASING PAND A ALTERING CASING PAND A ALTERING CASING PAND A ALTERING CASING PAND A
TEMPORARILY ABANDON
PULL OR ALTER CASING
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated de of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 09/13/18 MIRU plugging equipment. Removed horses head. POH w/ rods & pump. Dug out cellar, 09/14/18 ND well head, NU BOP. Set 5 ½" CIBP @ 2232'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 30 sx class C cmt @ 2232-1936 WOC. 09/17/18 Tagged plug @ 1844'. Spotted 25 sx class C cmt w/ 2% CACL @ 905-658'. WOC. Tagged plug @ 640'. Perf'd c @ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt @ 603' & circulated to surface. Rigged down & moved off. 109/22/18 Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated do of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 09/13/18 MIRU plugging equipment. Removed horses head. POH w/ rods & pump. Dug out cellar, 09/14/18 ND well head, NU BOP. Set 5 ½" CIBP @ 2232'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 30 sx class C cmt @ 2232-1936 WOC. 09/17/18 Tagged plug @ 1844'. Spotted 25 sx class C cmt w/ 2% CACL @ 905-658'. WOC. Tagged plug @ 640'. Perf'd c @ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt @ 603' & circulated to surface. Rigged down & moved off. (199/22/18) Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated do of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 09/13/18 MIRU plugging equipment. Removed horses head. POH w/ rods & pump. Dug out cellar, 09/14/18 ND well head, NU BOP. Set 5 ½" CIBP @ 2232'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 30 sx class C cmt @ 2232-1936 WOC. 09/17/18 Tagged plug @ 1844'. Spotted 25 sx class C cmt w/ 2% CACL @ 905-658'. WOC. Tagged plug @ 640'. Perf'd c @ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt @ 603' & circulated to surface. Rigged down & moved off. (19/22/18) Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 09/13/18 MIRU plugging equipment. Removed horses head. POH w/ rods & pump. Dug out cellar, 09/14/18 ND well head, NU BOP. Set 5 ½" CIBP @ 2232'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 30 sx class C cmt @ 2232-1936 WOC. 09/17/18 Tagged plug @ 1844'. Spotted 25 sx class C cmt w/ 2% CACL @ 905-658'. WOC. Tagged plug @ 640'. Perf'd c @ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt @ 603' & circulated to surface. Rigged down & moved off. 09/22/18 Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
proposed completion or recompletion. 09/13/18 MIRU plugging equipment. Removed horses head. POH w/ rods & pump. Dug out cellar, 09/14/18 ND well head, NU BOP. Set 5 ½" CIBP @ 2232'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 30 sx class C cmt @ 2232-1936 WOC. 09/17/18 Tagged plug @ 1844'. Spotted 25 sx class C cmt w/ 2% CACL @ 905-658'. WOC. Tagged plug @ 640'. Perf'd c @ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt @ 603' & circulated to surface. Rigged down & moved off. 109/22/18 Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
09/13/18 MIRU plugging equipment. Removed horses head. POH w/ rods & pump. Dug out cellar, 09/14/18 ND well head, NU BOP. Set 5 ½" CIBP @ 2232'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 30 sx class C cmt @ 2232-1936 WOC. 09/17/18 Tagged plug @ 1844'. Spotted 25 sx class C cmt w/ 2% CACL @ 905-658'. WOC. Tagged plug @ 640'. Perf'd c @ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt @ 603' & circulated to surface. Rigged down & moved off. @9/22/18 Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
BOP. Set 5 ½" CIBP @ 2232'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 30 sx class C cmt @ 2232-1936 WOC. 09/17/18 Tagged plug @ 1844'. Spotted 25 sx class C cmt w/ 2% CACL @ 905-658'. WOC. Tagged plug @ 640'. Perf'd c @ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt @ 603' & circulated to surface. Rigged down & moved off. 09/22/18 Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
BOP. Set 5 ½" CIBP @ 2232'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 30 sx class C cmt @ 2232-1936 WOC. 09/17/18 Tagged plug @ 1844'. Spotted 25 sx class C cmt w/ 2% CACL @ 905-658'. WOC. Tagged plug @ 640'. Perf'd c @ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt @ 603' & circulated to surface. Rigged down & moved off. 09/22/18 Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
@ 553'. Pressured up on perfs. ND BOP. Spotted 70 sx class C cmt @ 603' & circulated to surface. Rigged down & moved off. @ 9/22/18' Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
109/22/18 Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.
Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off. FINTEDIES NM OIL CONSERVATION
ENTERED NM OIL CONSERVATION ARTESIA DISTRICT
ENTERED NM OIL CONSERVATION ARTESIA DISTRICT
ARTESIA DISTRICT
OCT 0 9 2018
·
RECEIVED
Spud Date: Rig Release Date:
I hereby certify that the information above is true and complete to the best of my knowledge and belief.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE On DATE 10/4/18 Type or print name E-mail address: PHONE:
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE On DATE 10/4/18
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE On DATE 10/4/18 Type or print name E-mail address: PHONE: