Form 3160-5 (April 2004)

RECEIVED

UNITED STATES
DEPARTMENT OF THE INTERIOR

OCD Artesia

FORM AP	PROVED
OM B No.	1004-013

5. Lease Serial No.

PROVED	Diease ted 316
1004 -0137	to to w

BUREAU OF	LAND MA	NAGEMENT	MOA O	O.Thio	

SUNDRY NOTICES AND REPORTS ON WELLS LARTESIA O.C.D.

Do not use this form for proposals to drill of to re-enter an abandoned well Use Form 3160-3 (APD) for such proposals

NM-83032

6. If Indian, Allottee or Tribe Name

Do not use this									
	Use Form 3160-3 (A	•	•		7. If Unit of CA / Agreemen	t, Name and/or No.			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.									
1. Type of Well Oil Well	Gas Well		Other		8. Well Name and No. Texasville	Federal Com #1			
2. Name of Operator Yates Energy Corporation					9. API Well No. 30-015-26501				
3a. Address		3b. Phone No. ((include area code)	-	10. Field and Pool, or Explor				
P.O. Box 2323 Roswell, NI	VI 88202-2323	575-	623-4935		•	Point (Strawn)			
4. Location of (Footage, Sec., T., R., of	Survey Description)		*		11. County or Parish, State				
Sec 27 T2	3S R23E 2310FSL	. 1650FWL			Eddy	County, NM			
12. CHECK APPRO)PRIATE BOX(ES)	TO INDICATE	NATURE OF NO	OTICE, R	EPORT, OR OTHER DAT	ΓΑ			
TYPE OF SUBMISSION			7	TYPE OF A	ACTION				
Notice of Intent	Acidize		Deepen		oduction (Start/Resume)	Water Shut-off			
	Alter Casing		Fracture Treat		eclamation	Well Integrity			
Subsequent Report	Casing Repair		New Construction	□ Re	ecomplete	Other	•		
Final Abandonment Notice	Change Plans		Plug and Abandon	片で	emporarily Abandon				
Tinui Tiouride inieni Tionee	Convert to Inje	ection	Plug Back	⊔ wa	ater Disposal				
9/25/2018 MIRU. 9/26/2018 Unable to unset p 9/27/2018 Tag pkr @ 8612' s 9/28/2018 Circ well w/ MLF p 6939' TOC @ 6107 10/1/2018 Tag @ 6216' perf p 10/2/2018 Tag @ 3677' perf p 10/4/2018 Tag @ 607' perf @	et 4½ CIBP @ 860 pressure test 4½ g 7'. @ 4160' sqz 50 sx: @ 4105' pressure @ 2635' sqz 50 sx:	00' Tag @ 860 good @ 800 p s CTOC @ 40 up <u>BLM ok'd</u> s CTOC @ 24	si, spot 50 sxs 100'. to spot 25 sxs 195' Tag @ 2495	@ 4125' 5', perf @	00' TOC @ 7993' spot 5 TOC @ 3747'.	RECLAM DUE 4-1	ATION		
14. I hereby certify that the following is	s true and correct								
Name									
Chris Romero			Title		P&A Tech				
Signature CC 7			Date		19/9/18	ED FAD DEC			
	THIS S	PACE FOR F	EDERAL OR ST	TATE OF	FICE USE AUCEPT	EU FUR REC	עאט		
Approved by			Title		Date				
Conditions of approval, if any, are attac	hed. Approval of this n	otice does not			NO.	V 1 2018	 - - - - - - - - -		
warrant or certify that the applicant hold	ds legal or equitable title	to those rights				7 Y 7010			
in the subject lease which would entitle thereon.			Office		DINC	Consul LIE	- I		
Title 18 U.S.C., Section 1001 and Title any false, fictitious or fraudulent statem	43 U.S.C., Section 1212 ents or representations a	, make it a crime as to any matter w	for any person know within its jurisdiction	wingly and n.	willfully to make to any cleran	BADTRED OPFICE	United States		

		Fed Com No 1 1,650' FWL. Section	27 7 22 6 0 22		FIELD: COUNTY:	Bandana Poi		NM
		3 - 14) KB: 4,202	21, 1125-5, R125		SPUD DATE:	10/24/195		12/15/1990
	30-015-26501			Fed Lee No NM-83032	PREPARED E			
CASING:	DEPTH 350°	HOLE SIZE	13 3/8"	WEIGHT 48#	GRAD H-40	E THREAD ST&C	500 sx / Surface	NT / TOC
ASING:	2,585	12 1/4"	8 5/8	329	J&K-5		1,350 sx / Surface	
CASING:	8,800	7 7/8	4 1/2	11.6#	J-55	LT&C	650 sx / 6,326	
TUBING:								
I UBING:		P&A'd Actual	┶					
Skto Singiple 17 1/2**		10/4/18		Casing 8. Cement 13-38** Casing Cement Lead 150 ax Thorase w/ 1% Cal Gisorate + 1/4 pps calloftake Tai 350 ax Premium Plus w/ 2* celloftake	CI+10 pps % CaCI+1/4 pp	1 +	<u>Formation</u>	Tops & Depths
				9eri Saz notes @ 400 Establish circulation up 8-5% a 4- Close surface & test annulus to 70	1/2" annulus to	surface		
	AN			Mix & pump 110 sx "C" down 4-1/2	ow, OK " casing, out sq	ız hales	Captan	oud ⁻
	*****		\$ 72	@ 400' and circulate to surface Left 4-1/2" casing full of cement.		.	Brushy Canyon	1,100
	機能			Pert Sax hotes & 1.400	1		, ,,,,,	
	34	经 医	李 黎	Peri Saz holes @ 1.400* Mus & saz 190 sx "C" out saz holes Tag TOC @ 607	₽ 1 400°		Bone Springs Lime	1.459'
	- 30							
12 1/4"				8-5/8" Casing Cement Lead 100 sx Thisset wi 1% Cal Tail 1,000 ax HLW Premium Ph Tail 250 ax Premium Plus "C" w Circ 500 sx. TOC @ Surface	us "C" w/ 2% C v/ 2% CaCl + 1	aCI + % oos Flocele	ke 1st Bone Springs Sd	2.154'
	3			8 5/8" Csg @ 2,585"				
	•	1. 1	•	Peri Sat holes & 2,635 Mrv B sqt 50 sn "C" out tot holes &	, 475			
	۵			Tag TOC @ 2 495				
	,		' '	·				
	ġ	1	ļ					
			1				2nd Bone Springs Sd	3,303
	9	200352	'	Perf Sqr holes & 4.105				
	i.		_	Unable to pump into sqs holes Min & spot 250 sx "C" @ 4,125"				
	1			Tag TOC @ 3,677"				
	€		3	Pert Sat holes & 4,160" Mix & sat 50 ss "C" but sat holes &				
	E	20 Billion	ا الت	Mix 6 sqr 50 sx "C" out sqr holes @ 4 Tag TOC @ 4.135"	1,160			
	9		• -	· · · · · · · · · · · · · · · · · · ·				
	A	1 , 1	ı					
	•							
		· ·	ŧ					
		1 ' \ 1	7					
	ė	4 *	1					
	•	[. ;]	•					
	à		1					
	•		•					
	ġ	\$4.9 5 .02	i					
	E		A					
	¥		2		_			
	Ć.		g)	Mix S Spot 56 sx "4" plug @ 6,939	.		3rd Bone Springs Sd	6,694'
	į.	多。据源 隐		140 LOC & E 51E.			Wolfcamp	6,860
7 7/8"	, e		A					
	Š		39	4-1/2" Casing Cement				
	2		23	Lead 650 ax 50/50 PP/Poz w/ 6	5 pps Sail +			
	6			3/10% CFR3 + 4/10% Halad-9				
	į.		猫					
	Y	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	類	Carc WB ar 9 5 ppg mod	1			
	🤅		副	Test 4-1/2" casing above CIBP & 8 600" good to 800# Mis & Spot 50 sx "H" prug & 8 600	,		Caco	7,915'
8 600"	· P	经		Calc FOC @ 7,993				
	— <i>}</i>	100 m	X		_			
	#		12/14/90 Strawn:) : Perf 8,839 - 8'687' w/ 2 spf (57 h	qles)		Strawn	8,616
2-3'8" Lo	. I		51	- 4-1/7" CSG @ 8,800"				
5et Pkr (8 612 m	note	F-14	13 '	70 sx PP plug @ 8,900*			Atoka	8,863*
	;		_					
	•							
	ţ	(Topera	~#	En 00 -+ 0 0 /			Marrow	9.374
	Į.	24	اب	50 sx PP plug @ 9,400*				
	4		1				Lwr Morrow	9.877

° €



BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 B. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nin



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612