UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

	Expires: January 31, 20
5.	Lease Serial No. NMNM108456

SUNDRY N	NOTICES AND REPORTS ON WELLS form for proposals to drill or to re-enter an
Do not use this	form for proposals to drill or to re-enter an
	Use form 3160-3 (APD) for such proposals

C ICL II Aller T T N

abandoned wei	II. Use form 3160-3 (APD) 1	for such proposals.] '	o. If Indian, Allottee or	Tribe Name
SUBMIT IN T	TRIPLICATE - Other instruc	ctions on page 2	7	. If Unit or CA/Agreem	ent, Name and/or No.
Type of Well	ner		8	8. Well Name and No. KIAWAH BFQ FEDI	ERAL 1
2. Name of Operator EOG Y RESOURCES INC	Contact: TIN E-Mail: tina_huerta@e	NA HUERTA eogresources.com	9	O. API Well No. 30-015-38095-00	-S1
3a. Address 104 S 4TH STREET ARTESIA, NM 88210		o. Phone No. (include area code) h: 575-748-4168	1	0. Field and Pool or Ex UNDESIGNATED	
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			1. County or Parish, St	ate
Sec 34 T20S R25E NWSW 23	310FSL 400FWL	CC 12-17- ccepted for record - NM	OCD	EDDY COUNTY,	NM
12. CHECK THE AI	PPROPRIATE BOX(ES) TO) INDICATE NATURE OF	F NOTICE, R	EPORT, OR OTHE	ER DATA
TYPE OF SUBMISSION		TYPE OF	ACTION	· · · · · · · · · · · · · · · · · · ·	
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production	n (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamati	on	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	■ New Construction	□ Recomple	te	☐ Other
☐ Final Abandonment Notice	Change Plans	□ Plug and Abandon	□ Temporar	ily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Dis	posal	
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final Aldetermined that the site is ready for from the EOG Y Resources, Inc. plans 1. MIRU all safety equipment 2. RIH with bit and scraper 27 3. Set a CIBP at 2788 ft with Tag TOC. 4. Set a CIBP at 1040 ft with WOC. Tag TOC. 5. Perforate at 852 ft. Attempt 6. If no circulation see step 7. 7. Spot a 35 sx (188 ft) Class casing shoe.	operations. If the operation results and onment Notices must be filed clinal inspection. to plug and abandon this we as needed. POOH with prod 88 ft. So so f Class C cement on to 100 ft Class C ce	s in a multiple completion or recomby after all requirements, including all as follows: uction equipment. op. This will cover the top of the copy of	mpletion in a nering reclamation, Record 7 C: 17 Yeso. WOC San Andres 940 asing.	winterval, a Form 3160- have been completed and control of the form To See T	4 must be filed once d the operator has 95/8" F. Perf/South Perf/South Perf/South Perf/South Perf South Perf S
	Electronic Submission #443 For EOG Y RES itted to AFMSS for processing		arichad	19DLM0111SE) DE(2 1 2 2018
THAT HOL		Table 14200E			CETVED
Signature (Electronic	Submission)	Date 11/12/20	018		CEIVED
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE US	E	
_Approved By	a. ans	Title	PET		11-29-18 Date
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condition	uitable title to those rights in the su		0		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crit statements or representations as to	ne for any person knowingly and any matter within its jurisdiction.	willfully to mak	e to any department or a	gency of the United

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



Additional data for EC transaction #443768 that would not fit on the form

32. Additional remarks, continued

8. Spot a 150 sx Class C cement plug circulating cement back to surface between the 7 inch and 9-5/8 inch casing and a 188 ft cement plug inside the 7 inch casing from 940 ft ? 752 ft. This will cover the 9-5/8 inch casing shoe. WOC. Tag TOC.
9. Spot a 25 sx Class C cement plug from 150 ft up to surface.
10. Cut off wellhead and install dry hole marker. Clean location.

Wellbore schematics attached

WELL NAME: Kiawah BFQ Federal #1 FIELD:	
LOCATION: 2310' FNL & 400' FWL Sec. 34-20S-25E	
GL: <u>3370'</u> ZERO: KB:	
COMMENTS: API No.: 30-015-38095	

14-3/4"Hole 9-5/8* casing @ 802°. Cemented with 670sx circulated to surface. 8 3/4" Hole 🔏 Yeso Perforations @ 2838' – 2890' 7" casing @ 3600'. Cemented w/ 555 sx circulated to surface. TD: 3600' PBTD: 3555'

CASING PROGRAM

9-5/8" 36# K-55	802'	
7" 26# J-55	3600'	

Before

Formations		
Tops	Depth (ft)	
San Andres	990	
Glorieta	2658	
Yes >	2802	

Not to Scale 11/4/2018 SAA

LOCATION: 2310' FNL & 400' FWL Sec. 34-20S-25E		CASING PROG	RAIN
GL: <u>3370'</u> ZERO : KB:	9-5/8" 36#	K-55 80	2'
COMMENTS: API No.: 30-015-38095			
	7" 26# J-55	36	00'
	l I	<u> </u>	
150' (25sx) d	ass "C" cement plug from		
150' to surfac	Se.	A.£	
		Aft	ter
		h	
		Format	1
14-3/4" Hole		Tops	Depth (ft)
		San Andres	990
		Glorieta	2658
}/[:]/\		Yes	2802
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
Perforations @	9 852'. Class "C" cement		
-5/8" casing @ 802'. Cemented with piug from 940' covering 9-5/8	-752' inside the 7" casing		
70sx circulated to surface.	duding onso.		
CIBP @ 1040' with 1 cement on top coveri			
8 3/4" Hole Andres.	ing top or our		
CIBP @ 2788' w/ 25s.			
Comen covering top C	or the reso.		
Yeso Perforations @			
2838' – 2890'			
		31-44-	Cools
		Not to 11/4/20	
		1 11141711	י ומו

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.