Submit 1.Copy To Appropriate District	State of New Me			Form C-103
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	Revised July 18, 2013
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVA NIDQIDEQNO FRVA		TION	30-015-23242
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	ict III - (505) 334-6178 1220 South St. Francis Dr. DISTRIC			of Lease K FEE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	⁷ 58N 17 2019	STATE 6. State Oil & G	
87505				1857-2
SUNDRY NOTICES AND REPORTS ON WELLS PECEIVED (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Travis 24 St
1. Type of Well: Oil Well X	Gas Well Other		8. Well Number #1	
2. Name of Operator Matador Production Company			9. OGRID Numl	per 228937
3. Address of Operator 5400 LBJ Freeway Suite 1500 Dallas TX 75240			10. Pool name or Wildcat Loco Hills, Wolfcamp NW	
4. Well Location				
· ·	feet from the NORTH	line and 660		om the EAST line
Section	24 Township 18S Ra 11. Elevation (Show whether DR,	ange 28E . <i>RKB. RT. GR. etc.)</i>	NMPM	County Eddy
	3524'			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK				ALTERING CASING
TEMPORARILY ABANDON				
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEIVIEN	1306	
CLOSED-LOOP SYSTEM OTHER:	Recomplete X	OTHER:		П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
MIRU, Kill Well				
Set CIBP @ 8608 (current Wolfcamp perfs: 8658-8722') Spot 35' Cl H cmt on top of CIBP. WOC. Tag. Pressure Test.				
Perf Wolfcamp +/- 8384-8540 & Acidize.				
Swab to test. If productive, RWTP. If unproductive, set CIBP 50' above top of perfs & spot 35' Cl H cmt. WOC. Tag. Pressure Test				
Perforate Bone Spring at +/- 8118-8140'. Acidize. Swab. RWTP.				
		<u> </u>		
Spud Date: 8/31/19	90 Rig Release Da	ate:		
L .		<u> </u>		 J
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE //	TITLE Engir			ATE
Type or print name Chris Villarreal E-mail address:PHONE: (972) 371-5471				
Conditions of Approval (if any): TITLE SUSSILES (AB) PRE 1-23-2019				
APPROVED BY: With the TITLE Business Conspect DATE 1-23-2019 Conditions of Approval fif any): Verhalgues 40 Was Monroe 40 proceed with work on 1-23-2019				



